HNF-EP-0182, Rev. 155

# Waste Tank Summary Report for Month Ending February 28, 2001

Prepared for the U.S. Department of Energy Assistant Secretary for Environmental Management



# CH2MHILL

Hanford Group, Inc.

Richland, Washington

Contractor for the U.S. Department of Energy Office of River Protection under Contract DE-AC08-99RL14047

Approved for Public Release; Further Dissemination Unlimited

THIS PAGE INTENTIONALLY LEFT BLANK

#### LEGAL DISCLAIMER ..

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced from the best available copy. Available in paper copy and microfiche.

Available electronically at <a href="http://www.doc.gov/bridge">http://www.doc.gov/bridge</a>. Available for a processing fee to the U.S. Department of Energy and its contractors, in paper, from: U.S. Department of Energy Office of Scientific and Technical Information P.O. Box 62 Oak Ridge, TN 37831-0062

Oak Ridge, TN 37831-0062 phone: 865-576-8401 fax: 865-576-5728

email: reports@adonis.osti.gov(423) 576-8401

Available for sale to the public, in paper, from: U.S. Department of Commerce National Technical Information Service 5285 Port Royal Road Springfield, VA 22161 Phone: 800-553-6847

fax: 703-605-6900

email: orders@ ntis.fedworld.gov

online ordering:

http://www.ntis.gov/ordering.htm

Printed in the United States of America

# THIS PAGE INTENTIONALLY LEFT BLANK

S

#### **ENGINEERING CHANGE NOTICE**

Page 1 of \_\_\_\_\_\_

1. ECN 667128

2. ECN Category (mark one) 4. USQ Required? 5. Date 3. Originator's Name, Organization, MSIN, and Telephone No. B. M. Hanlon, Inventory & Flowsheet Eng. Supplemental **⊠** No ☐ Yes 03/19/01 R3-72, 373-2053 X Direct Revision 6. Project Title/No./Work Order No. 7. Bidg/Sys/Fac. No. 8. Approval Designator Change ECN Waste Tank Summary Report for Temporary Month Ending February 28, 2001 N/A N/A Standby Document Numbers Changed by this ECN (includes sheet no. and rev.) 10. Related ECN No(s). 11. Related PO No. Supersedure HNF-EP-0182, Rev. 154 Cancel/Void N/A N/A 12d. Restored to Original Condition (Temp. or Standby ECNs only) 12c. Modification Work Completed 12a. Modification Work 12b. Work Package No. ☐ Yes (報) out Blk, 12b) <u> N/A</u> No (NA Blks. 12b. 12c, 12d) N/A Design Authority/Cog. Engineer Signature & Date Design Authority/Cog. Engineer Signature & 13a. Description of Change 13b. Design Baseline Document? Yes Complete revision Computer generated: File: \\APOO1\TWRSSHAR\SHARE\BETTYH 1\HNF-EP 1 Size: 7.18MB (7,531,520 bytes) Wednesday, MARCh 21, 2001 11:23:18 Am Modified: Monday, March 19, 2001 2:11:50 PM 14a. Justification (mark one) 14b. Justification Details This ECN is being generated to update waste tank farm summary Criteria Change information. **Design Improvement Environmental Facility Deactivation** As-Found Facilitate Const. Const. Error/Omission Design Error/Omission 15. Distribution (include name, MSIN, and no. of copies) **RELEASE STAMP** Distribution list attached following document HANFORD ID.

									1. ECN (	ise no. from	1 pg. 1)
	E	NGINEERII	NG CHANGE	NOTICE			Page 2 of	2	) e	67128	
16 Decian Verification	17. Cost im	inect					90 2 0		<u> </u>	dule Impact	(dave)
16. Design Verification Required	17. 005.	ENGINEER	ING .		CC	NSTR	UCTION		10. 00110	acio impao.	(Guyb)
☐ Yes	Additional	<b>-</b> \$		Additional		<b>s</b>			improvem	ent 🔲 _	
⊠ No	Savings			Savings					Delay		
. —	, -	he related docum	nents (other than the	-	docum	ents id	entified on	Side 1) that		cted by	
19. Change impact Revi	d in Block 13.	Enter the affect	ed document number	in Block 20.			J.,	0.00 ., 0.0.	***************************************	02 2,	,
SDD/DD			Seismic/Stress	Analysis				Tank Ca	libration Ma	nual	
Functional Design C	riteria		Stress/Design	Report				Health P	hysics Proc	edure	
Operating Specifical	tio <del>n</del>	므	Interface Cont	roi Drawing				Spares !	Multiple Unit	Listing	
Criticality Specificati	ion		Calibration Pro	ocedure				Test Pro	cedures/Sp	ecification	
Conceptual Design	Report		Installation Pro	ocedure				Compon	ent Index		
Equipment Spec.			Maintenance F	Procedure		□		ASME C	oded item		
Const. Spec.		Ö	Engineering P	rocedure				Human i	actor Cons	ideration	
Procurement Spec.			Operating Insti	ruction				Compute	r Software		
Vendor Information			Operating Proc					Electric (	Circuit Sche	dule	
OM Manual			Operational Sa	ifety Require	ment			ICRS Pr			
FSAR/SAR			IEFD Drawing						Control Ma		
Safety Equipment Li			Cell Arrangeme	•					Flow Chart		
Radiation Work Peri			Essential Mate	•					e Requisitio 	n	
Environmental Impa			Fac. Proc. San	•				Tickler F	ile		
Environmental Repo			Inspection Plan		4	님			<del></del>	<del></del>	
Environmental Perm			Inventory Adju						45 445 1		
20 Other Afferdari Deals			MEG DESIGN MISS SIGN DE		B CU	1. 30	ueinier de	KOM NUTICALE	marrie ad	กเหอ	
20. Other Affected Documents organization has been	n notified of o	ther affected doc	uments listed below.								
_	n notified of o t Number/Rev			t Number/Re					ent Numbe		
Documen	t Number/Rev										
Documen											
Documen	t Number/Rev										
Documen	t Number/Rev		Documen					Docum		r/Revision	
Documen N	t Number/Rev						Signatur	Docum			·
Documen N 21. Approvais Design Authority	t Number/Rev	ision	Documen		vision	**		Docum		r/Revision	•
Documen N 21. Approvais Design Authority	t Number/Rev	ision	Documen	t Number/Re	vision	**		Docum		r/Revision	•
Documen  N  21. Approvais  Design Authority  Cog. Eng. B.M. Ha	t Number/Rev	Lanlon	Dete 3/19/01	t Number/Re  Design	vision	**		Docum		r/Revision	•
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K	t Number/Rev	Lanlon	Documen	Design	n Agel	**		Docum		r/Revision	ė
Documen  N  21. Approvais  Design Authority  Cog. Eng. B.M. Ha	t Number/Rev	Lanlon	Dete 3/19/01	t Number/Re  Design	n Agel	**		Docum		r/Revision	e
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K	t Number/Rev	Lanlon	Dete 3/19/01	Design	n Agel	**		Docum		r/Revision	•
Documen  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design	n Agei	**		Docum		r/Revision	•
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design	n Agei	**		Docum		r/Revision	•
Documen  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design	n Agei	**		Docum		r/Revision	•
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design	n Agei	**		Docum		r/Revision	•
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design	n Agei	**		Docum		r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro	n Agel	nt	Signatur	Docum		r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro	n Agel	nt	Signatur	Росит	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	nt	Signatur	Docum	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	NT OF	Signatur	Росит	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	NT OF	Signatur	Росит	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	NT OF	Signatur	Росит	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	NT OF	Signatur	Росит	ent Numbe	r/Revision	
Document  N  21. Approvals  Design Authority  Cog. Eng. B.M. Ha  Cog. Mgr. N. W. K  QA  Safety  Environ.	t Number/Rev	Lanlon	Dete 3/19/01	Design PE QA Safety Design Enviro Other	n Agel	NT OF	Signatur	Росит	ent Numbe	r/Revision	

# Waste Tank Summary Report for Month Ending February 28, 2001

B. M. Hanlon CH2M HILL Hanford Group, Inc.

Date Published February 2001

Prepared for the U.S. Department of Energy Assistant Secretary for Environmental Management

# CH2MHILL Hanford Group, Inc.

P. O. Box 1500 Richland, Washington

Contractor for the U.S. Department of Energy Office of River Protection under Contract DE-AC06-99RL14047

Approved for Public Release; Further Dissemination Unlimited

# (1) Document Number **RECORD OF REVISION** HNF-EP-0182 Page 1 (2) Title WASTE TANK SUMMARY REPORT FOR MONTH ENDING FEBRUARY 28, 2001 Change Control Record Authorized for Release (4) Description of Change - Replace, Add, and Delete Pages (3) Revision (5) Cog. Engr. (6) Cog. Mgr. Date EDT-631372 BM Hanlon JS Garfield 153 Bn Hienlon BM Hanlon NW Kirch 3/21/01 155 RS Incorporation of ECN-667128

A-7320-005 (10/97)

### WASTE TANK SUMMARY REPORT FOR MONTH **ENDING FEBRUARY 28, 2001**

#### BM HANLON

CH2M HILL Hanford Group, Inc. Richland, WA 99352 U.S. Department of Energy Contract DE-AC27-99RL14047

EDT/ECN: ECN-667128

UC:

Cost Center:

Charge Code:

B&R Code:

Total Pages: 90

Key Words: REPORT, WASTE TANK SUMMARY

Abstract: See page iii of document

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

Printed in the United States of America. To obtain copies of this document, contact: Document Control Services, P.O. Box 950, Mailstop H6-08, Richland WA 99352, Phone (509) 372-2420; Fax (509) 376-4989.

CROTILAH

**Approved For Public Release** 

This page intentionally left blank.

#### Waste Tank Summary Report

#### B. M. Hanlon

#### **ABSTRACT**

(i) This report is the official inventory for radioactive waste stored in underground tanks in the 200 Areas at the Hanford Site. Data that depict the status of stored radioactive waste and tank vessel integrity are contained within the report. This report provides data on each of the existing 177 large underground waste storage tanks and 63 smaller miscellaneous underground storage tanks and special surveillance facilities, and supplemental information regarding tank surveillance anomalies and ongoing investigations. This report is intended to meet the requirement of U. S. Department of Energy-Richland Operations Office Order 435.1 (DOE-RL, July 1999, Radioactive Waste Management, U. S. Department of Energy-Richland Operations Office, Richland, Washington) requiring the reporting of waste inventories and space utilization for Hanford Tank Farm tanks.

This page intentionally left blank.

#### HNF-EP-0182, Rev. 155

#### TABLE OF CONTENTS

		Page
SU	MMARY	1
I.	WASTE TANK STATUS	1
Π.	WASTE TANK INVESTIGATIONS	1
Ш.	SURVEILLANCE AND WASTE TANK STATUS HIGHLIGHTS	2
App	pendixes:	
<b>A</b> . :	MONTHLY SUMMARY	A-1
	Tables: 1 Monthly Summary	A-2
	2 Tank Ties Commons	A-3
	3 Pumping Record, and Liquid Status and Pumpable Liquid Remaining in Tanks	A-4
	4 Inventory Summary by Tank Farm	А-Э
	5 Inventory and Status by Tank - Double-Shell Tanks	A-6
	6 Inventory and Status by Tank - Single-Shell Tanks	A-8
R ·	PERFORMANCE SUMMARY	B-1
<b>.</b> .	Table:	
	1 Summary of Waste Transactions in the Double-Shell Tanks	<u>B-2</u>
	2 Comparison of Projected Versus Actual Waste Volumes for Hanford Facilities	B-3
<b>C</b> . 3	DOUBLE-SHELL TANK WASTE TYPE AND SPACE ALLOCATION	C-1
	Tables: 1 Double-Shell Tank Waste Inventory	C-2
	2 Double-Shell Tank Available Space	C-3
	Figures:	
	1 Total Double-Shell Tank Inventory	C-4
ъ	WASTE TANK SURVEILLANCE MONITORING TABLES	D-1
D.	Tables:	,
	1 Temperature Monitoring in Watch List Tanks	D-2
	2 Temperature Monitoring in Non-Watch List Tanks	D-4
	3 Additions/Deletions to Watch List Tanks by Year	D-5
	4 Single-Shell Tank Monitoring Compliance Status	D-6
	5 Double-Shell Tanks Monitoring Compliance Status	D-12
	6 FNRAF Surface Level Gauge Installation and Data Input Methods	D-14
	7 Tank Monitor and Control System (TMACS)	D-15
F .	MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL	
سو	SURVEILLANCE FACILITIES	E-1
	Tables:	
	1 Misc Underground Storage Tanks and Special Surveillance Facilities (Active)	E-2
	2. East Area Underground Storage Tanks and Special Surveillance Facilities (Inactive)	E-3
	3 West Area Underground Storage Tanks and Special Surveillance Facilities (Inactive)	E-4
F.	LEAK VOLUME ESTIMATES	F-1
г	Table:	
	1 Single-Shell Tank Leak Volume Estimates	F-2
	The state of the s	

#### HNF-EP-0182, Rev. 155

G. SINGLE-SHELL TANKS INTERIM STABILIZATION, AND CONTROLLED,	
CLEAN, AND STABLE (CCS) STATUS	G-1
Tables:	
1 Single-Shell Tanks Interim Stabilization Status	G-2
2 Single-Shell Tank Interim Stabilization Milestones	G-4
3 Single-Shell Tanks Stabilization Status Summary	
H. TANK AND EQUIPMENT CODE AND STATUS DEFINITIONS	H-1
1 Tank and Equipment Code/Status Definitions	
I. TANK FARM CONFIGURATION, STATUS AND FACILITY CHARTS	I -1
1 High-Level Waste Tank Configuration	I-2
2 Double-Shell Tank Instrumentation Configuration	
3 Single-Shell Tank Instrumentation Configuration	

М	ETRIC CONV	ERSION CHART	
1 inch		2.54 centimeters	
1 foot	=	30.48 centimeters	
l gallon	=	3.80 liters	
1 ton	_	0.90 metric tons	
	$^{\circ}F = \left(\frac{9}{5}\right)$		
	1 Btu/h = 2.930 (Internatio	711 E-01 watts nal Table)	

#### WASTE TANK SUMMARY REPORT For Month Ending February 28, 2001

Note: Changes from the previous month are in bold print.

#### I. WASTE TANK STATUS

Category	Quantity	Date of Last Change
Double-Shell Tanks <sup>b</sup>	28 double-shell	10/86
Single-Shell Tanks	149 single-shell	1966
Assumed Leaker Tanks	67 single-shell	07/93
Sound Tanks	28 double-shell 82 single-shell	1986 07/93
Interim Stabilized Tanks	126 single-shell	02/01
Not Interim Stabilized <sup>a</sup>	23 single-shell	02/01
Intrusion Prevention Completed	108 single-shell	09/96
Controlled, Clean, and Stable <sup>f</sup>	36 single-shell	09/96
Watch List Tanks <sup>d</sup> Total	19 single-shell 5 double-shell 24 tanks	09/00° 01/00

Of the 126 tanks classified as Interim Stabilized, 65 are listed as Assumed Leakers. (See Table G-1)

#### II. WASTE TANK INVESTIGATIONS

This section includes all single- or double-shell tanks or catch tanks which are showing surface level or interstitial liquid level (ILL) decreases, or drywell radiation level increases in excess of established criteria.

<sup>&</sup>lt;sup>b</sup> Five double-shell tanks (SY-101 was removed from the list in January 2001) are currently included on the Hydrogen Watch List and are thus prohibited from receiving waste in accordance with "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991, November 5, 1990, Public Law 101-510.

Two of these tanks are Assumed Leakers (BY-105, BY-106). (See Table F-1)

<sup>&</sup>lt;sup>4</sup> See Appendix D for more information on Watch List Tanks.

Dates for the Watch List tanks are "officially added to or removed from the Watch List" dates. Eighteen tanks were removed from the Organic Watch List in December 1998; the last two tanks (C-102 and C-103) were removed from the Organic Watch List in August 2000. In December 1999, tank C-106 was removed from the High Heat Load Watch List. Only the Hydrogen Watch List remains.

<sup>&</sup>lt;sup>f</sup> The TY tank farm was officially declared Controlled, Clean, and Stable (CCS) in March 1996. The TX tank farm and BX tank farms were declared CCS in September 1996.

#### A. Assumed Leakers or Assumed Re-leakers: (See Appendix H for definition of "Re-leaker")

This section includes all single- or double-shell tanks or catch tanks for which an off-normal or unusual occurrence report has been issued, or for which a waste tank investigation is in progress, for assumed leaks or re-leaks. Tanks/catch tanks will remain on this list until either a) completion of Interim Stabilization, b) the updated occurrence report indicates that the tank/catch tank is not an assumed leaker, or c) the investigation is completed.

There are no formal leak investigations in progress. There are no tanks for which an off-normal or unusual occurrence report has been issued for assumed leaks or re-leaks.

#### B. Tanks with increases indicating possible intrusions:

This section includes all single-shell tanks and related receiver tanks for which the surveillance data show that the surface level or ILL has met or exceeded the increase criteria, or are still being investigated.

Candidate Intrusion List: Increase criteria in the following tanks indicate possible intrusions.

Tank 241-B-202 Tank 241-BX-101 Tank 241-BX-103 Tank 241-BY-103

The surveillance data was last reviewed on the tanks listed as having probable liquid intrusions: Memo 74B20-99-045, dated November 22, 1999.

Catch Tank 241-AX-152: The liquid level in this catch tank was steady around 66.75 inches from the startup of Project W-030, "Tank Farm Ventilation System," in March 1998 until late August 1998. The level then began to decrease. The October 1998 reading of 65 inches is 1.75 inches below the summer average. This is an active catch tank, routinely pumped, and deviations from baseline are not applicable per OSD-00031. The decrease represents a significant change in trend and it is apparent that tank conditions changed around the end of August 1998.

Resolution Status: Discrepancy Report #98-853 was issued on November 4, 1998. One possible cause under investigation is a change in flow path, causing an increase in evaporation. The tank was pumped down to 2.25 inches on November 13, 1998. Since that time the level has decreased to 0.00 inches. The Discrepancy Report will remain open until an engineering investigation is complete.

The discrepancy remained unresolved, and there was a renewed interest in this tank because of its importance for deactivation of the 702A ventilation system to prepare it for Decommissioning and Deactivation and for collection of drainage from AX-155. In the absence of an agreement on a leak test, management requested a leak assessment. The leak assessment team met April 20, 2000, to review the data. Observations inconsistent

with a conclusion that the catch tank was leaking and scanty data prompted the leak assessment team to defer a decision pending availability of additional data - primarily tank temperature and a more sensitive level measuring device to shorten the necessary leak test time. A Leak Test Recommendation was issued May 8, 2000. The leak test involves adding water to the tank and measuring the level drop, to support tank integrity assessment. The addition of AX-152 integrity pressure test water to AY-101 is being reevaluated because the actual volume of water to be added to the DST system is considerably more than the volume originally evaluated. The increased volume is necessary because of the siphon type pump in the catch tank.

Leak assessment is currently being performed per Work Package 2E-00-193. Water was added in August 2000 which raised the level to 10.75 inches. The level was 8.50 inches on February 28, 2001.

Work Package 2E-00-194 is on the schedule to fill the catch tank to 80% capacity (approximately 108 inches) and perform a 40-hour leak test.

Because the ENRAF will not be installed, Work Package ES-99-00133 has been revised to allow flammable gas sampling through the existing manual tape.

#### III. SURVEILLANCE AND WASTE TANK STATUS HIGHLIGHTS

#### 1. Single-Shell Tank Interim Stabilization

Tank 241-S-106 was Interim Stabilized on February 1, 2001. Total Waste: 455.3 Kgal; Supernate: none; DIL and DLR: 28.1 Kgal; PLR: 18.2 Kgal; Saltcake: 455.3 Kgal; no Sludge. Total Pumped: 203.6 Kgal, including waste pumped during previous campaigns.

2. Single-Shell Tanks Saltwell Jet Pumping (See Table A-6 footnotes for further information)

Tank 241-A-101 - Pumping began May 6, 2000. No pumping since August 2000; a total of 14.1 Kgallons has been pumped from this tank since start of pumping in May 2000.

Tank 241-AX-101 - Pumping began July 29, 2000. No pumping since August 2000; a total of 8.3 Kgallons has been pumped from this tank since start of pumping in July 2000.

Tank 241-S-102 - Pumping problems forced many shutdowns. The pump was replaced and pumping resumed on February 19, 2000. Problems with the new pump forced a shutdown on March 23, 2000. Pumping was interrupted in early June 2000; due to the flushing involved in trying to return to pumping, June pumping resulted in a net addition to the tank. No pumping since June 2000; a total of 56.8 Kgallons has been pumped from this tank since start of pumping in March 1999.

Tank 241-S-109 - Pumping began September 23, 2000. The pumping rate dropped below 0.05 GPM and the pump was shut down on January 27, 2001. The tank is now being evaluated to determine if it can be Interim Stabilized. A total of 145.2 Kgallons has been pumped from this tank (111.0 Kgallons were pumped in 1979 [primary stabilization], and partial isolation in 1982).

Tank 241-SX-101 - Pumping began November 22, 2000. In December 2000, a total of 6.9 Kgallons was pumped; a total of 19.2 Kgallons has been pumped from this tank. The pump failed on December 9, 2000. No pumping since December 2000.

Tank 241-SX-103 - Pumping began October 26, 2000. In February 2001, a total of 6.0 Kgallons was pumped; a total of 110.0 Kgallons has been pumped from this tank since start of pumping in October 2000.

Tank 241-SX-105 - Pumping began August 8, 2000. In February 2001, a total 1.8 Kgallons was pumped; a total of 151.1 Kgallons has been pumped since start of pumping in August 2000.

Tank 241-U-102 - Pumping began January 20, 2000. No pumping in February 2001; a total of 74.0 Kgallons has been pumped from this tank since start of pumping in January 2000.

Tank 241-U-105 - Pumping began December 10, 1999, and was discontinued July 13, 2000, because of a pump failure. Waste levels are being allowed to stabilize, so waste porosities and final waste volumes can then be calculated to determine whether this tank meets Interim Stabilization criteria.

Tank 241-U-106 - Pumping began August 24, 2000. In December 2000, a total of 0.7 Kgallons was pumped; a total of 39.1 Kgallons has been pumped from this tank since start of pumping in August 2000. Pumping rate has fallen below 0.05 GPM. The pump failed on December 29, 2000. The tank is currently in observation mode to determine eligibility for interim stabilization.

Tank 241-U-109 - Pumping began March 11, 2000. In December 2000, a total of 0.6 Kgallons was pumped; a total of 65.9 Kgallons has been pumped from this tank since start of pumping in March 2000. Jet pump failure occurred on December 4, 2000. Attempts to restart the pump have been unsuccessful. The tank is currently under observation mode to determine eligibility for interim stabilization with major equipment failure.

3. RP-CHG-TANKFARM-2001-0004, Occurrence Report, "Corrosion Observed in DST Tank 241-AY-101 During Video Inspection of the Annulus Section," Off-Normal Occurrence, Notification Date: January 31, 2001.

Corrosion of the primary and secondary liners of DST AY-101 was observed during video inspections of the tank annulus region in 1999 and 2000. Follow-up video inspections that were completed on January 29, 2001, show more extensive corrosion in localized regions of the

#### HNF-EP-0182, Rev. 155

primary and secondary liners when viewed from the annulus region. There are no visual or radiological indications of waste leakage from the tank.

An operational restriction has been imposed to limit the waste level in this tank to less than 80 inches until further evaluation can be performed.

4. RP-CHG-TANKFARM-2001-0006, Occurrence Report, "Flammable Gas Level Exceeds Lower Flammability Limit (LFL) at 241-C-101 Riser 1," Off-Normal Occurrence, Updated: February 9, 2001.

While performing the required initial flammable gas monitoring at C-101 Riser 1, the flammable gas level was found to be greater than 25% LFL. A grab sample taken when was opened will be analyzed for additional information. The riser was immediately secured in a safe condition. This work activity was in preparation for installation of a buoyancy type (ENRAF) tank liquid level measuring device.

All work was stopped per the work instruction. Additional flammable gas monitoring samples taken at the C-101 Breather Filer and Manual Tape access points indicated 0% LFL. A grab sample was taken for additional analysis. The riser was then secured in a safe condition. Entry restrictions were put in place.

The processes to obtain the results of the gas sampling analysis is continuing.

#### HNF-EP-0182, Rev. 155

This page intentionally left blank

# APPENDIX A MONTHLY SUMMARY

# TABLE A-1. MONTHLY SUMMARY TANK STATUS

Februry 28, 2001

	200	200	
	EAST AREA	<b>WEST AREA</b>	TOTAL
IN SERVICE	25	03	28 (1)
OUT OF SERVICE	66	83	149
SOUND	59	51	110
ASSUMED LEAKER	32	35	67
INTERIM STABILIZED	60	66	126
ISOLATED			
PARTIAL INTERIM	11	30	41
INTRUSION PREVENTION COMPLETE	55	53	108
CONTROLLED, CLEAN, AND STABLE	12	24	36

		WASTE VOLUM	MES (Kgallons)	)		-	
		200	200		SST	DST	
,		EAST AREA	<b>WEST AREA</b>	IOTAL	<b>TANKS</b>	TANKS	IOTAL
SUPERN	ATANT						
AW	Aging waste	1763	0	1763	0	1763	1763
cc	Complexant concentrate waste	3170	1263	4433	0	4433	4433
CP	Concentrated phosphate waste	1088	0	1086	0	1088	1088
DC	Dilute complexed waste	1715	831	2546	1	2545	2546
DN	Dilute non-complexed waste	1656	0	1856	0	1656	1656
PD	PUREX/TRUsolids	316	0	316	0	316	316
NCPLX	Non-complexed waste	164	149	313	313	ø	313
DSSF	Double-shell slurry feed	6031	168	6199	1049	5150	6199
TOTAL	LSUPERNATANT	15903	2411	18314	1363	16951	18314
SOLIDS				•			
Słudg	e (includes liquids)	6459	5648	12107	11059	1048	12107
Salto	ske (includes liquids)	8106	15910	24016	20808	3208	24016
TOTA	AL SOLIDS	14565	21558	36123	31867	4256	36123
TC	ITAL WASTE	30468	23969	54437	33230	21207	54437
AVAILA	BLE SPACE IN TANKS	9283	806	10089	0	10089	10089
DRAINA	BLE INTERSTITIAL LIQUID (2)	1425	2026	3451	3451	(2)	3451
DRAINA	BLE LIQUID REMAINING (2)	2472	2342	4814	3906	(2)	3906

<sup>(1)</sup> Includes five double-shell tanks on Hydrogen Watch List not currently allowed to receive weste, AN-103, AN-104, AN-105, AW-101, and SY-103. SY-101 was removed from the Hydrogen Watch List in January 2001and will return to service later in the year.

<sup>(2)</sup> Drainable Interstitial Liquid and Drainable Liquid Remaining for single-shell tanks only; not applicable for double-shell tanks

TABLE A-2. TANK USE SUMMARY February 28, 2001

					ISOLATED TAN		
	TANKS AVAILABLE			PARTIAL	INTRUSION	CONTROLLED	INTERIM
TANK	TO RECEIVE		<b>ASSUMED</b>	INTERIM	PREVENTION	CLEAN, AND	STABILIZED
FARMS	<u>WASTE TRANSERS</u>	<u>SOUND</u>	LEAKER	ISOLATED	<u>COMPLETED</u>	STABLE	<u>IANKS</u>
EAST							
A	O	3	3	2	4	0	5
AN	7 (1)	7	0	0	0	0	0
<b>AP</b>	8	8	. 0	0	0	0	0
AW	6 (1)	6	0	0	0	0	0
ΑX	0	2	2	1	3	0	3
AY	2	2	0	0	0	0	0
AZ	2	2	0	0	0	0	0
В	0 ·	6	10	0	16	. 0	16
ВX	0	7	5	0	12	12	12
3Y	0	7	5	5	7	0	10
	0	9	7	3	13	0	14
Total	25	59	32	11	55	12	80
WEST							
S	0	11	1	10	2	0	6
SX	0	5	10	6	9	0	11
SY	3 (1)	3	0	0	0	0	0
T	0	9	7	5	11	0	16
ΤX	0	10	8	0	18	18	18
TY	0	1	5	0	6	6	6
J	0	12	4	9	7	. 0	9 .
Total	3	51	35	30	53	24	66
TOTAL	28	110	67	41	108	36	126

<sup>(1)</sup> Five Double-Shell Tanks on the Hydrogen Watch List are not currently receiving waste transfers (AN-103, 104, 105, AW-101, and SY-103).

SY-101 was removed from the Hydrogen Watch List in January 2001 and will return to service later in the year.

# TABLE A-3. PUMPING RECORD, LIQUID STATUS AND PUMPABLE LIQUID REMAINING IN TANK FARMS

February 28, 2001

			Waste Vo	olumes (Kgallons)			
			CUMULATIVE		DRAINABLE	DRAINABLE	PUMPABLE
TANK	PUMPED	PUMPED FY	TOTAL PUMPED	SUPERNATANT	INTERSTITIAL	LIQUID	SST LIQUID
<i>EARMS</i> EAST	THIS MONTH	TO DATE	1979 TO DATE	LIQUID	REMAINING	REMAINING	REMAINING
A	0.0	0.0	164.6	503	161	665	622
AN	N/A	N/A	N/A	3745	N/A	N/A	N/A
AP	N/A	N/A	N/A	6279	N/A	N/A	N/A
AW	N/A	N/A	N/A	2489	N/A	N/A	N/A
AX	0.0	0.0	21.3	378	105	483	447
AY	N/A	N/A	N/A	581	N/A	N/A	N/A
AZ	N/A	N/A	N/A	1763	N/A	N/A	N/A
В	0.0	0.0	0.0	15	262	277	203
BX	N/A	0.0	200.2	24	127	N/A	N/A
BY	0.0	0.0	1567.8	0	581	581	498
C	0.0	0.0	103.0	126	189	315	207
Total	0.0	0,0	2066.9	15903	1425	2321	1977
WEST							
S	0.0	21.7	1075.1	76	636	712	578
SX	7.8	201.5	659.1	134	326	460	387
SY	N/A	N/A	N/A	2094	N/A	N/A	N/A
T	0.0	0.0	245.7	29	218	246	168
TX	N/A	0.0	1205.7	9	297	N/A	N/A
TY	N/A	0.0	29.9	0	53	N/A	N/A
U	0.0	31.3	365.4	69	496	565	483
Total	7.8	254.5	3580.9	2411	2026	1983	1816
TOTAL	7.8	254.5	5637.8	18314	3451	4304	3593

N/A = Not applicable for Double-Shell Tank Farms, and Single-Shell Tank Farms which have been declared Controlled, Clean and Stable (BX, TX, TY).

#### TABLE A-4. INVENTORY SUMMARY BY TANK FARM February 28, 2001

				Ş	SUPERN	IATANT	LIQUIL	O VOL	UMES (	Kgallo		SOLID	S VOLUM	1E
TANK	TOTAL	AVAIL											SALT	
<u>EARM</u>	WASTE	SPACE	_AW	<u>cc</u>	CP	DC	DN	PD	NCPLX	DSSE	TOTAL	SLUDGE	_CAKE	TOTAL
EAST														
<b>A</b>	1479	0	0	o	0	0	0	0	0	503	503	574	402	976
AN	5489	2487	0	1780	0	0	224	0	0	1741	3745	0	1748	1748
AP	6368	2752	0	1390	1088	1605	37	0	0	2159	6279	0	89	89
AW	3982	2858	0	0	0	0	923	316	0	1250	2489	571	922	1493
AX	826	0	0	0	0	0	0	0	0	378	378	26	422	448
AY	830	1130	0	0	0	109	472	0	0	0	581	249	0	249
AZ	1920	56	1763	0	0	0	0	0	0	0	1763	157	0	157
В	1909	0	0	0	0	0	0	0	15	0	15	1211	683	1894
BX	1490	0	0	0	0	0	0	0	24	0	24	1259	207	1486
BY	4387	0	0	0	0	0	0	0	0	0	0	754	3633	4387
С	1784	0	0	0	0	1	. 0	0	125	0	128	1658	0	1658
Total	30484	9281	1763	3170	1082	1715	1850	318	184	8031	15903	5459	8106	14565
WEST														
S	5056	0	۰	0	0	0	0	0	75	1	76	1184	3796	4980
sx	3734	0	0	0	0	0	o	0	0		134	927	2673	3600
SY	2614	806	٥	1263	0	831	0	o	o		2094	71	449	520
т	1877	0	0	0	0	0	0	0	29		29	1703		1848
TX	6810	0	٥	0	o	0	0	0	9		9	697	6104	6801
TY	639	0	١	0	0	0	0	0	0		0	529		639
υ	3239	o	0	0	0	0	0	0			69	537	2633	3170
Total	23969	806	o	1263	ø	031	G	0	149	168	2411	5849	15910	2156
TOTAL	54433	10089	1763	4433	1048	2546	1856	316	313	6199	18314	12107	24016	\$612

TABLE A-5. INVENTORY AND STATUS BY TANK - DOUBLE-SHELL TANKS

February 28, 2001

		TANK	STATUS					<u> </u>	SOLID	S VOLUME			PHOTOS/	VIDEOS	<u> </u>
								[	SLUDGE		SALTCAKE				SEE
				EQUIVA-		AVAIL.	SUPER-	SLUDGE	LIQUID	SALTCAKE	CIQUID				FOOTNOT
				LENT	TOTAL	SPACE	NATANT	(includes	(15%	(includes	(25%	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	TANK	WASTE	WASTE	(1)	LIQUID	liquid)	porosity)	(figuidi	porosity)	VOLUME	IN-TANK	IN-TANK	THESE
TANK_	MATL	STATUS	USE	NCHES	(Kgøl)	(Kgal)	(Kgal)	(Kgal)	(Kg#)	(Kgal)	(Kgal)	UPDATE	PHOTO	VIDEO	CHANGES
						<del>-</del>									
								<u>ANK FAR</u>	<u>M STATU</u>	<u>8</u>					
AN-101	DN	SOUND	DRCVR	<b>8</b> 1.5	224	916	224	0	0	0	0	06/30/99			}
AN-102	CC	SOUND	CWHT	383.6	1055	85	966	0	0	89	22	06/30/99			1
AN-103	DSS	SOUND	CWHT	347.6	956	184	499	0	0	457	114	06/30/99	10/29/87		1
AN-104	DSSF	SOUND	CWHT	382.5	1052	88	603	0	0	449	112	06/30/99	08/19/88		<b>!</b>
AN-105	DSSF	SOUND	CWHT	410.2	1128	12	639	0	0	489	122	06/30/99	01/26/88		1
AN-106	CC	SOUND	CWHT	13.6	38	1102	21	0	0	17	4	06/30/99			i
AN-107	CC	SOUND	CWHT	378.2	1040	100	793	0	0	247	82	06/30/99	09/01/88		1
							Ļ	<b></b>					<b> </b>		<b>└</b> ──
DOUBL	E-SHELL T	ANKS		TOTALS	<u>5493</u>	2487	3745		0	1748	436	L	<u> </u>		
								A 2017 P. A 201		_					
	2005		55 cm (5	405.4				ANK FAR					ì		1
AP-101	DSSF	SOUND	DRCVR	405.1	1114	26	1114	0	0		0	05/01/69			Į.
AP-102	CP	SOUND	DRCVR	395.6	1068	52	1086	0	0	0	0	07/11/89	1		1
AP-103	CC	SOUND	DRCVR	102.5	282	858	282	0	0	0	0	05/31/96	4		l
AP-104	CC	SOUND	DRCVR	402.9	1108	32	1108	0	o	0	0	10/13/88	•		.]
AP-105	OSSF	SOUND	CWHT	412.4	1134	6	1045	0	0	89	22	06/30/99	ł.	09/27/9!	<b>'</b> }
AP-106	DC	SOUND	DRCVR	226.2	622	518	622	0	0	Ō	0	10/13/88	•		1
AP-107	DC	SOUND	DRCVR	357.5	983	157	983	0	0	o	0	10/13/88	l		1
AP-108	DN	SOUND	DRCVA	13.5	37	1103	37	0	O	0	0	10/13/88	[		I
								<del> </del>				L	<del>}</del>		4
DOUBL	E-SHELL T	ANKS		TOTALS	6368	2752	6279		0		22		L		J
						A	W TANK	PADM CT	ATHE						
AW-101	DSSF	SOUND	CWHT	409.5	1126	14	751	0	0 <u>1108</u>	375	94	10/31/00	03/17/88		1
AW-102	DN	SOUND	EVFD	315.6	868	272	838		ŏ	30	8	01/31/01	02/02/83		1
AW-102	PD	SOUND	DACVR		508	632	145	316	79	47	12	06/30/99	[		1
AW-104	DN	SOUND	DRCVR	114.9	316	824	85	0	0	231	58	06/30/99			Į.
			DRCVA		426	714	171	255	38	231	0	06/30/99	-		ĺ
AW-105	PO DSSF	SOUND		154.9 268.4	738	402	499	255	36 0	239	60	1	T .		
AW-106	DOOF	SOUND	SRCVR	200.4	738	402	499	1	U	239	<del>0</del> 0	06/30/99	VZ/VZ/63		1
DOUBL	E-SHELL T	ANKC		TOTALS	3982	2858	2489	571	117	922	232	<u> </u>	<del> </del>		4
) DOVDL	E OFFICE I	WIAK 2		IUIALS	3702	2000	2400	1	'_'				I		

#### TABLE A-5. INVENTORY AND STATUS BY TANK - DOUBLE-SHELL TANKS

#### February 28, 2001

		TANK	STATUS										PHOTO	S/VIDEOS	<u> </u>
				EQUIVA- LENT	TOTAL	AVAIL. SPACE	SUPER- NATANT	SLUDGE (Includes	SLUDGE LIQUID (15%	SALTCAKE (includes	SALTCAKE LIQUID (25%	SOLIDS	LAST	LAST	SEE FOOTNO FOR
	WASTE	TANK		WASTE	WASTE	(1)	LIGUID	liquid)	porosity)	liquid)	poroeityi	VOLUME	IN-TANK PHOTO	IN-TANK VIDEO	THESE
TANK	MATL	STATUS	USE	INCHES	(Kgal)	(Kgal)	(Kgel)	(Kgal)	(Kgal)	(Kgal)	(Kgel)	UNDAIL	molu	VIDEO	CHANGE
							AY TA	NK FARM	STATUS						
Y-101	DC	SOUND	DRCVR	67.3	186	795	109	76	11	0	0	06/30/99	12/28/82		1
NY-102	DN	SOUND	DRCVR	234.5	645	335	472	173	28	0	0	10/31/00	04/28/81		
DOUBL	E-SHELL 1	TANKS		TOTALS	830	1130	581	249	39	0	0				
							AZ TA	NK FARM	STATUS						
Z-101	AW	SOUND	CWHT	336.0	924	56	872	52	8	0	0	06/30/98	08/18/83		ı
AZ-102	AW	SOUND	DACVR	362.2	996	0	891	105	16	0	0.	06/30/99	10/24/84		
DOUBL	E-SHELL	TANKS		TOTALS	1920	56	1763	157	24	o	0	<u> </u>			<u> </u>
							SY TA	NK FARM	STATUS						
Y-101	CC	SOUND	CWHT	352.7	970	170	887	0	0	63	21	06/30/99	04/12/89		1
Y-102	DC	SOUND	DRCVR	328.0	902	238	831	71	11	0	0	06/30/99	04/29/81		
SY-103	œ	SOUND	CWHT	269.8	742	398	376	0	0	366	92	06/30/99	10/01/65		
DOUBL	LE-SHELL	TANKS		TOTALS	2614	808	2094	71	11	449	113				
	TOTAL				21207	10089	18951	1048	191	3208	803		<del>                                     </del>		

Note: +/- 1 Kgal differences are the result of computer rounding

Available Space C	int	
Tank Farms	(Most Conservative)	
AN, AP, AW, SY	1,140,000 gal (414.5 ln.)	1,140 Kgal
AY, AZ (Aging Weste)	980,000 gal (356.4 in.)	980 Kgal

NOTE: Supernate + Sludge (includes liquid) + Saltcake (includes liquid) = Total Waste

<sup>(1)</sup> Available Space volumes include restricted space, - see Appendix C tables for allocation of these restrictions.

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS
February 28, 2001

		*174					09600000000000000000	1021 y 20,	oboconoccionocunacion							
<u></u>			volumes a	re we re	SOU DI	engmeer				tol agree			rei nicesur			
	TANK S	TATUS			<b>}</b> _		LIQ	NID NOTO			SOLIDS	VOLUME		PHOTOS/	VIDEOS	<u> </u>
					10.1550	DRAIN-			DRAIN-	PUMP-	1					SEE
				T0T44	SUPER-	ABLE	PUMPED	~~~	ABLE	ABLE	<u> </u>					FOOTNOT
	****	*****	STABIL/	TOTAL	NATE	INTER-	THIS	TOTAL	LIQUID	LIQUID	[	SALT	SOLIDS	LAST	LAST	FOR
TANK	WASTE MAT'L.	TANK INTEGRITY	ISOLATION STATUS	WASTE (Kgal)	(Kgal)	STIT. (Kgal)	MONTH	PUMPED	REMAIN		SLUDGE		VOLUME	IN-TANK	IN-TANK	THESE
TANK	WIA L.	MIEGNITT	317103	(Kgal)	(IV)) and	IMBall	(Kgal)	(Inglai)	(Kgel)	(Kgal)	(Kgai)	(Kgal)	UPDATE	PHOTO	AIDEO	CHANGES
							A TAI	<u>VK FARM</u>	STATUS							_
A-101	DSSF	SOUND	/PI	877	494	95	0.0	14.1	590	574	3	380	09/30/99	08/21/85		(a)
A-102	DSSF	SOUND	IS/PI	41	4	8	0.0	39.5	12	4	15	22	07/27/89	07/20/89		1
A-103	DSSF	ASMD LKR	is/ip	371	5	45	0.0	111.0	50	43	366	0	06/03/88	12/28/88		j
A-104	NCPLX	ASMO LKR	is/ip	28	0	4	0.0	0.0	4	0	28	0	01/27/78	06/25/86		ļ
A-105	NCPLX	ASMD LKR	IS/IP	37	0	0	0.0	0.0	0	0	37	0	10/31/00	08/20/86		l
A-108	CP	SOUND	IS/IP	125	0	9	0.0	0.0	9	1	125	0	09/07/82	08/19/86		l
6 SINGL	E-SHELL 7	ANKS	TOTALS	1479	503	161	0.0	164.6	665	622	574	402				<b></b> -
	-						AW 77.4	NIZ IZ A DA	COTATE							<del></del>
AX-101	Dect	SOUND	/PI	676	378	74	0.0	NK FARM 8.3		400	١ .	205	ا معرممرهما			1
AX-101		ASMD LKR	IS/IP	30	0	7	0.0	13.0	452 7	436	3	295	09/30/99 06/30/99	08/18/87		(h)
AX-102		SOUND	IS/IP	112	0	23	0.0	0.0	23	0	7	23		06/05/89		ļ
AX-103		ASMO LKR	IS/IP	8	0	23 1	0.0	0.0	23 <sub>.</sub>	11	8	104	06/30/99 06/30/99	08/13/87 08/18/87		Į.
									<u> </u>				00,00,00	50,10,01		L
4 SINGL	E-SHELL 1	ANKS	TOTALS:	826	378	105	0.0	21.3	483	447	26	422				
							B TAN	K FARM	STATUS							
B-101	NCPLX	ASMD LKR	IS/IP	113	0	24	0.0	0.0	24	17	0	113	06/30/99	05/19/83		1
B-102	NCPLX	SOUND	IS/IP	32	4	7	0.0	0.0	11	4	0	28	06/30/99	08/22/86		4
B-103	NCPLX	ASMO LKR	IS/IP	59	0	11	0.0	0.0	11	3	0	59	06/30/99	10/13/88		ļ
B-104	NCPLX	SOUND	IS/IP	371	1	45	0.0	0.0	46	42	309	61	06/30/99	10/13/88		
B-105	NCPLX	ASMD LKR	IS/IP	158	0	20	0.0	0.0	20	16	28	130	06/30/99	05/19/88		İ
B-106	NCPLX	SOUND	IS/IP	117	1	25	0.0	0.0	26	19	0	116	02/29/00	02/28/85		1
B-107	NCPLX	ASMO LKR	IS/IP	165	1 1	22	0.0	0.0	23	19	93	71	06/30/99	02/28/85		Į.
B-100	NCPLX	SOUND	IS/IP	94	0	15	0.0	0.0	15	11	53	41	06/30/99	05/10/85		ľ
B-109	NCPLX	SOUND	IS/IP	127	0	21	0.0	0.0	21	17	63	64	06/30/99	04/02/85		1
B-110	NCPLX	ASMD LKR	IS/IP	246	1	27	0.0	0.0	28	20	245	0	02/28/85	03/17/88		1
B-111	NCPLX	ASMD LKR	IS/IP	237	1	23	0.0	0.0	24	29	236	0	06/28/85	06/26/86		<b>S</b>
B-112	NCPLX	ASMO LKR	IS/IP	33	3	4	0.0	0.0	7	3	30	0	05/31/85	05/29/85		ł.
B-201	NCPLX	ASMO LKR	IS/IP	29	1	4	0.0	0.0	5	1	28	0	04/28/82	11/12/86	06/23/95	1
B-202	NCPLX	SOUND	IS/IP	27	0	4	0.0	0.0	4	0	27	0	05/31/85	05/29/85	06/15/95	<b>:</b> ]
B-203	NCPLX	ASMD LKR	IS/IP	51	1	5	0.0	0.0	6	1	50	0	05/31/64	11/13/86		ſ
B-204	NCPLX	ASMO LKR	IS/IP	50	1	5	0.0	0.0	6	1	49	0	05/31/84	10/22/87		ţ
18 5100	LE-SHELL	TANKS	TOTALS	1909	15	262	0.0	0.0	277	203	1211	683	<del> </del> -			<del> </del> -
10 2840	re-snell	CANA	TOTALS	1 309	<u></u>	702	<u> </u>	<u></u>	211	203	1211	563	L	L,		<u> </u>

HNF-EP-0182, Rev. 155

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS February 28, 2001

		These	yolumes a	re the re	anii of e	ng inger	000000000000000000000000000000000000000	istonia	900000000000000000							
<u></u>	TANK S		**************************************	<u></u>	**********	u viciosist		UID VOLU		نبند لنقيش		VOLUME	نسسمنسالسة	PHOTOS	Minene	
	IANK	ITATOS			<del>                                     </del>	DRAIN-	LR	OID VOLU	DRAIN-	PUMP-	SUCIUS	AOLOME		riiolos	VIDEUS	SEE
						ABLE	PUMPED		ABLE	ABLE	İ					FOOTNO
			STABIL/	TOTAL	SUPER-	INTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE		VOLUME	IN-TANK	IN-TANK	THESE
TANK	MAT'L.	INTEGRITY	STATUS		(Kgal)	(Kgal)	(Kgal)		(Kgal)	(Kgal)	(Kgal)	(Kgal)	UPDATE	PHOTO	VIDEO	CHANGE
							BY TAI	NK FARM	STATES					<u> </u>		<u> </u>
RY-101	NCPLX	ASMD LKR	IS/IP/CCS	43	1 1	4	0.0	0.0	5	1	42	0	M/28/82	11/24/88	11/10/94	1
	NCPLX	ASMD LKR	IS/IP/CCS	96	ا ا	0	0.0	0.0	0	ò	96	o		09/18/85	.,,,,,,,	l
	NCPLX	SOUND	IS/IP/CCS	71	ı ,	4	0.0	0.0	13	9	62	o o	į	10/31/86	10/27/94	l
	NCPLX	SOUND	IS/IP/CCS	93	3	4	0.0	17.4	7	3	90	Ö		09/21/89		İ
	MCPLX	SOUND	IS/IP/CCS	51	J 5	4	0.0	15.0	9	5	48	ō	-	10/23/86	•	
	NCPLX	SOUND	IS/IP/CCS	38	ه ا	4	0.0	14.0	4	0	38	0		05/19/88	07/17/96	[
BX-107	NCPLX	SOUND	IS/IP/CCS	345	l i	36	0.0	23.1	37	33	344	0	09/18/90	09/11/90		
BX-108	NCPLX	ASMD LKR	15/IP/CCS	26	0	4	0.0	0.0	4	0	26	0	07/31/79	05/05/94		
BX-109	NCPLX	SOUND	IS/IP/CCS	193	0	25	0.0	8.2	25	20	193	0	09/17/90	09/11/90		{
BX-110	NCPLX	ASMD LKR	IS/IP/CCS	207	3	28	0.0	1.5	31	26	133	71	06/30/99	07/15/94	10/13/94	
BX-111	NCPLX	ASMD LKR	IS/IP/CCS	162	1	5	0.0	116.9	8	2	25	138	06/30/99	05/19/94	02/28/95	ı
BX-112	NCPLX	SOUND	IS/IP/CCS	165	1	9	0.0	4.1	10	7	164	0	09/17/90	09/11/90		
12 SING	LE-SHELL	TANKS	TOTALS:	1490	24	127	0.0	200.2	151	106	1259	207				
							BY TA	NK FARM	STATUS							
BY-101	NCPLX	SOUND	IS/IP	387	] 0	28	0.0	35.0	28	24	109	278	05/30/84	09/19/89		Į.
BY-102	NCPLX	SOUND	IS/PI	277	0	40	0.0	159.0	40	33	0	277	05/01/95	09/11/87	04/11/95	[
BY-103	NCPLX	ASMD LKR	IS/PI	400	0	58	0.0	95.9	58	53	9	391	06/30/99	09/07/89	02/24/97	·
BY-104	NCPLX	SOUND	IS/IP	326	0	40	0.0	329.5	40	36	150	176	06/30/99	04/27/83		ļ
BY-105	NCPLX	ASMD LKR	/PI	503	0	121	0.0	0.0	121	111	48	455	08/31/99	07/01/86		1
BY-106	NCPLX	ASMO LKR	/Pi	562	0	132	0.0	63.7	132	119	84	478	12/31/98	11/04/82		
BY-107	NCPLX	ASMD LKR	IS/IP	26 <del>6</del>	0	39	0.0	56,4	39	35	40	226	06/30/99	10/15/86		}
BY-108	NCPLX	ASMD LKR	IS/IP	228	0	33	0.0	27.5	33	26	154	74	04/28/82	10/15/86		1
BY-109	NCPLX	SOUND	IS/PI	290	0	31	0.0	157.1	31	26	57	233	07/08/87	06/18/97		
BY-110	NCPLX	SOUND	IS/IP	398	( 0	21	0.0	213.3	21	17	103	295	1	07/26/84		ł
BY-111	NCPLX	SOUND	IS/IP	459	0	14	0.0	313.2	14	6	0	459	06/30/99	10/31/86		
BY-112	NCPLX	SOUND	IS/IP	291	0	24	0.0	116.4	24	12	0	291	06/30/99	04/14/88		
12 SING	ILE-SHELL	TANKS	TOTALS:	4387	-	581	0.0	1567.8	581	496	754	3633				

February 28, 2001

	745***		e volumes a	ae the n	sult of	enginee				nei (dere	7		yel mesm	entenis		
	TANK	STATUS			<u> </u>	2	LIQ	UID VOLU			SOLIDS	VOLUME				<del></del> _
					1	DRAIN-			DRAIN-	PUMP-	ł					SEE
					l	ABLE	PUMPED		ABLE	ABLE	ļ					FOOTNOT
			STABIL		SUPER	INTER-	THIS	TOTAL	LIQUID	FIGNID		SALT	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	-	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE		VOLUME	IN-TANK	IN-TANK	
TAN	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgəl)	(Kgai)	(Kgal)	(Kgai)	(Kgal)	(Kgal)	UPDATE	PHOTO	VIDEO	CHANGES
					_		C TAI	NK FARM	STATUS							
C-10	1 NCPLX	ASMD LKR	IS/IP	88	0	4	0.0	0.0	4	0	88	O	11/29/83	11/17/87		1
C-10	2 DC	SOUND	IS/IP	316	0	62	0.0	46.7	62	55	316	0	09/30/95	05/18/76	08/24/95	
C-10	3 NCPLX	SOUND	/P1	198	79	18	0.0	0.0	97	83	119	0	12/31/98	07/28/87		1
C-10	4 CC	SOUND	IS/IP	263	0	0	0.0	0.0	0	0	263	o	02/01/00	07/25/90		ļ
C-10	5 NCPLX	SOUND	IS/PI	132	0	20	0.0	0.0	20	0	132	0	02/29/00	08/05/94	08/30/95	ł
C-10	8 NCPLX	SOUND	/PI	46	42	0	0.0	0.0	42	9	6	0	10/31/99	08/05/94	08/08/94	ļ
C-10	7 DC	SOUND	IS/IP	257	0	30	0.0	40.8	30	25	257	0	06/30/99	00/00/00		ł
C-10	B NCPLX	SOUND	IS/IP	66	0	4	0.0	0.0	4	0	66	0	02/24/84	12/05/74	1,1/17/94	
C-10	9 NCPLX	SOUND	IS/IP	66	4	4	0.0	0.0	8	4	62	O	11/29/83	01/30/76		i
C-110	D DC	ASMD LKR	IS/IP	178	1	37	0.0	15.6	36	30	177	0	06/14/95	08/12/86	05/23/95	
C 11	1 NCPLX	ASMD LKR	IS/IP	57	0	4	0.0	0.0	4	0	57	0	04/28/82	02/25/70	02/02/95	
C-11:	2 NCPLX	SOUND	IS/IP	104	0	6	0.0	0.0	6	1	104	O	09/18/90	09/18/90	*	
C-20	1 NCPLX	ASMD LKR	IS/IP	2	0	0	0.0	0.0	0	0	2	0	03/31/82	12/02/86		ł
C-20	2 EMPTY	ASMO LKR	IS/IP	1	0	0	0.0	0.0	0	0	] 1	0	01/19/79	12/09/86		ļ
C-20	3 NCPLX	ASMD LKR	IS/IP	5	0	0	0.0	0.0	0	0	5	0	04/28/82	12/09/86		1
C-20	4 NCPLX	ASMO LKR	IS/IP	3	0	0	0.0	0.0	0	0	3	0	04/28/82	12/09/88		ł
16 S	NGLE-SHELI	TANKS	TOTALS:	1784	126	189	0.0	103.0	315	207	1658	0				
10.0.		· ·	TOTALO:	- 17.04	120	100		K FARM		207	1 1000					<u> </u>
S-10	T NCPLX	SOUND	/PI	427	12	83	0.0	0.0	95	80	211	204	12/31/98	03/18/88		1
S-10:	2 DSSF	SOUND	/PI	492	0	93	0.0	56.8	93	89	105	387	05/31/00			(c)
S-10:	3 DSSF	SOUND	IS/PI	237	1	45	0.0	23.9	46	39	9	227	04/30/00		01/28/00	
S-104	4 NCPLX	ASMD LKR	IS/IP	294	1	34	0.0	0.0	35	31	293	0	12/20/84	12/12/84	•	
S-10	5 NCPLX	SOUND	IS/IP	456	0	42	0.0	114.3	42	33	2	454	09/26/88	-		1
S-10	B NCPLX	SOUND	IS/PI	455	0	26	0.0	203.6	26	2	0	455	02/28/01	03/17/89	01/2B/00	(a)
S-10	7 NCPLX	SOUND	/PI	376	14	81	0.0	0.0	75	61	293	69	06/30/99	03/12/87		]
S-10	B NCPLX	SOUND	IS/PI	432	0	0	0.0	199.8	0	0	5	427	10/01/99	03/12/87	12/03/96	
S-10	NCPLX	SOUND	/P1	473	0	59	0.0	145.2	59	49	13	460	12/31/00		,	()
5-110	NCPLX	SOUND	IS/PI	390	0	30	0.0	203.1	30	27	131	259	05/14/92		12/11/96	•
S-11	NCPLX	SOUND	/21	501	48	82	0.0	3.3	130	97	116	337	09/30/99	08/10/89		1
S-11	NCPLX	SOUND	/PI	523	0	81	0.0	125.1	81	70	6	517	12/31/98	03/24/87		}
10.6	NOTE OUT	TANKS	TOTALO	Fore				4075 1	7.5		<del> </del>					<del> </del>
12 3	NGLE-SHELI	CANAL	TOTALS:	5056	76	6.36	0,0	1075.1	712	578	1184	3796				l

HNF-EP-0182, Rev. 155

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

February 28, 2001

								uary 20,	200 L							
		These	volumes a	e lie re	salt of c	ngnec	ing calcu	lations a	nd may :	ut egree	erik su		ie (necon	enent.		
	TANK S	TATUS			l		LIQ	UID VOLU	ME		SOLIDS	VOLUME				
						DRAIN-			DRAIN-	PUMP-						SEE
						ABLE	PUMPED		ABLE	ABLE	1					FOOTNOT
			STABIL	TOTAL	SUPER-	NTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	IN-TANK	IN-TANK	THESE
TANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgel)	(Kgal)	(Kgal)	(Kgel)	(Kgal)	UPDATE	PHOTO	VIDEO	CHANGES
		<u></u> , , <u>,</u>					SX TAI	NK FARM	STATUS							
8X-101	DC	SOUND	/PI	429	1 0	93	0.0	19.2	93	80	1 0	429	12/31/00	03/10/89		1 m
SX-102		SOUND	/PI	514	134	95	0.0	0.0	229	216	ا	380	04/30/00	01/07/68		[ "
SX-103		SOUND	/PI	524	0	37	6.0	110.0	37	22	115	409	01/31/01	12/17/87		(k)
5X-104		ASMD LKR	IS/PI	446		48	0.0	231.3	48	44	136	310	04/30/00	09/08/88	02/04/98	
SX-105		SOUND	/PI	486	0	2	1.6	151.1	2	-10	85	421	-1/31/01	06/15/88	- ,	(n)
	NCPLX	SOUND	IS/PI	397	0	37	0.0	147.5	37	31	0	397	05/31/99	06/01/89		
	NCPLX	ASMD LKR	IS/IP	102	0	0	0.0	0.0	0	0	85	17	10/31/00	03/06/87		
	NCPLX	ASMD LKR	IS/IP	67	0	0	0.0	0.0	0	0	87	0	12/31/93	03/06/87		ł
SX-109	NCPLX	ASMD LKR	IS/IP	249		. 0	0.0	0.0	0	0	60	189	10/31/00	05/21/86		
<b>SX-110</b>	NCPLX	ASMD LKR	IS/IP	62	0	0	0.0	0.0	0	0	62	0	10/08/76	02/20/87		
SX-111	NCPLX	ASMD LKR	IS/IP	122	0	8	0.0	0.0	6	3	122	0	06/30/99	06/09/94		
SX-112	NCPLX	ASMD LKR	IS/IP	108	0	6	0.0	0,0	6	1	106	0	06/30/99	03/10/67		
SX-113	NCPLX	ASMD LKR	IS/IP	31	0	0	0.0	0.0	0	0	31	0	06/30/99	03/18/88		
SX-114	NCPLX	ASMD LKR	IS/IP	165	0	0	0.0	0.0	0	0	44	121	10/31/00	02/26/87		
SX-115	NCPLX	ASMD LKR	IS/IP	12	0	0	0.0	0.0	0	0	12	0	04/28/82	03/31/88		
15 SING	LE-SHELL	TANKS	TOTALS:	3734	134	326	7.8	659,1	460	387	927	2673				
							T TAN	K FARM	STATUS							
T-101	NCPLX	ASMD LKR	IS/PI	102	1	20	0.0	25.3	21	16	37	64	06/30/99	04/07/93		Į.
T-102	NCPLX	SOUND	IS/IP	32	13	3	0.0	0.0	16	. 11	19	0	08/31/84	06/28/89		
T-103	NCPLX	ASMD LKR	IS/IP	27	4	3	0.0	0.0	7	3	23	0	11/29/83	07/03/84		1
T-104	NCPLX	SOUND	IS/PI	317	0	31	0.0	149.5	31	27	317	0	12/31/99	06/29/89	10/07/99	l
T-105	NCPLX	SOUND	IS/IP	98	0	5	0.0	0.0	5	0	96	0	05/29/87	05/14/87		
T-106	NCPLX	ASMD LKR	IS/IP	21	2	0	0.0	0.0	2	2	19	0	04/28/82	06/29/89		
T-107	NCPLX	ASMD LKR	IS/PI	173		34	0.0	11.0	34	20	173	0	05/31/96	07/12/84	05/09/96	3
T-106	NCPLX	ASMD LKR	IS/IP	44	0	5	0.0	0.0	5	0	21	23	06/30/99	07/17/84		

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS
February 28, 2001

\$900000000000	******	(((((((((((((((((((((((((((((((((((((((		000000000000000000000000000000000000000	9000000000000000	****	letesoateeccoocee	iuaiy 20,	000000000000000000000000000000000000000	**********	200000000000000000000000000000000000000	950000000000000000000000000000000000000			200000000000000000000000000000000000000	000000000000000000000000000000000000000
		These	volumes a	re the re	sult of	mgineer	ing calci	ilations a	nd may i	of agree	with su	rface le	rei measu	ements		
	TANK S	TATUS					LIO	NIO VOLUI	ME		SOLIDS	VOLUME				
				-		DRAIN-			DRAIN-	PUMP-						SEE
					Ĭ	ABLE	PUMPED		ABLE	ABLE	[					FOOTNOTE
			STABIL/	TOTAL	SUPER-	INTER-	THIS	TOTAL	FIGUID	LIQUID	1	SALT	SOLIDS	LAST	LAST	FOR
	WASTE	TANK	ISOLATION	WASTE	NATE	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	IN-TANK	IN-TANK	THESE
TANK	MAT'L.	INTEGRITY	STATUS	(Kgal)	(Kgal)	(Kgal)	(Kgel)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	UPDATE	PHOTO	VIDEO	CHANGES
T-109	NCPLX	ASMO LKR	IS/IP	58	l 0	10	0.0	0.0	10	3	l 0	58	06/30/99	02/25/93		1
T-110	NCPLX	SOUND	IS/PI	369	Ĭ	48	0.0	50.3	48	43	368	0	01/31/00	07/12/84	10/07/99	i
T-111	NCPLX	ASMD LKR	IS/PI	446	ه ا	38	0.0	9.6	38	35	446	ō	04/18/94	04/13/94		
T-112	NCPLX	SOUND	IS/IP	67	,	4	0.0	0.0	11	7	60	0	04/28/82	08/01/84	02,1400	1
T-201	NCPLX	SOUND	IS/IP	29	1	4	0.0	0.0	5	1	28	0	05/31/78			į.
T-202	NCPLX	SOUND	IS/IP	21		3	0.0	0.0	3	Ö	21	o	07/12/81	07/06/89		1
T-203	NCPLX	SOUND	IS/IP	35	0	. 6	0,0	0.0	5	Ö	35	o	01/31/78	08/03/89		)
T-204	NCPLX	SOUND	IS/IP	38	0	5	0.0	0.0	5	0	38	0	07/22/81	08/03/89		1
											ļ		ļ			<del> </del>
16 SM	BLE-SHELL	TANKS	TOTALS:	1877	29	218	0.0	245.7	246	168	1703	145	<u> </u>	L		<u></u>
TX TANK FARM STATUS																
TX-101	NCPLX	SOUND	IS/IP/CCS	87	3	8	0.0	0.0	11	7	74	10	06/30/99	10/24/85		
TX-102	NCPLX	SOUND	IS/IP/CCS	217	0	27	0.0	94.4	27	16	0	217	08/31/84	10/31/85		Į.
TX-103	NCPLX	SOUND	IS/IP/CCS	157	0	18	0.0	68.3	18	11	0	157	06/30/99	10/31/85		ľ
TX-104	NCPLX	SOUND	IS/IP/CCS	65	6	9	0.0	3.6	14	9	23	37	06/30/99	10/16/84		1
TX-105	NCPLX	ASMD LKR	IS/IP/CCS	609	0	25	0.0	121.5	25	14	0	609	08/22/77	10/24/89		
TX-106	NCPLX	SOUND	IS/IP/CCS	341	0	37	0.0	134.6	37	30	) 0	341	06/30/99	10/31/95		]
TX-107	NCPLX	ASMO LKR	IS/IP/CCS	36	1	6	0.0	0.0	7	1	8	27	06/30/99	10/31/85		1
TX-108	NCPLX	SOUND	IS/IP/CCS	134	0	8	0.0	13.7	8	1	6	128	06/30/99	09/12/89		1
TX-109	NCPLX	SOUND	IS/IP/CCS	384	0	6	0.0	72.3	6	2	384	0	06/30/99	10/24/89		į.
TX-110	NCPLX	ASMD LKR	IS/IP/CCS	462	0	14	0.0	115.1	14	10	37	425	06/30/99	10/24/89		!
TX-111	NCPLX	SOUND	IS/IP/CCS	370	0	10	0.0	98.4	10	6	43	327	06/30/99	09/12/89		1
TX-112	NCPLX	SOUND	IS/IP/CCS	649	0	26	0,0	94.0	26	21	0	649	05/30/83	11/19/87		Į.
TX-113	NCPLX	ASMO LKR	IS/IP/CCS	653	0	30	0.0	19.2	30	0	0	653	10/31/00	04/11/83	09/23/94	il .
TX-114	NCPLX	ASMO LKR	IS/IP/CCS	535	0	17	0.0	104.3	17	11	4	531	06/30/99	04/11/83	02/17/98	<b>5</b> ]
TX-115	NCPLX	ASMD LKR	IS/IP/CCS	568	) 0	25	0.0	99.1	25	15	0	5 <b>68</b>	06/30/99	06/15/88		1
TX-116	NCPLX	ASMO LKR	IS/IP/CCS	631	0	21	0.0	23.6	21	17	68	563	06/30/99	10/17/89		l
TX-117	NCPLX	ASMD LKR	IS/IP/CCS	626	0	10	0.0	54.3	10	5	29	597	06/30/99	04/11/83		
TX-118	NCPLX	SOUND	IS/IP/CCS	286	0	o	0,0	89.1	0	0	21	265	02/01/00	12/19/79	•	1
18 SING	3LE-SHELL	TANKS	TOTALS:	6810	9	297	0.0	1 205.7	306	176	697	6104	<del> </del>	<del> </del> -		<del> </del>
	OFFEE								~~~		1 007	0,07		<u></u>		<del></del>

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS
February 28, 2001

	200000000000000000000000000000000000000	<b>0000000000000000000000000000000000000</b>	*************	200000000000000000000000000000000000000		********	*********	rcui	wary 20,	2001 ************	*********		000000000000000000000000000000000000000		*************		
			These	volumes a	o ilone	solt of	41) Y I 1 0 e I	ne calc	italikak i		i (Cirja)	wiili su	fiere la	rel meason	(2HS/119)		
		TANK S	TATUS					LIO	UID VOLU	ME_		SOLIDS	VOLUME		PHOTOS/		
							DRAIN-			DRAIN-	PUMP-						SEE
						SUPER-	ABLE	PUMPED		ABLE	ABLE	<b>!</b>					FOOTNOTES
				STABIL/	TOTAL	NATE	INTER-	THIS	TOTAL	LIQUID	LIQUID		SALT	SOLIDS	LAST	LAST	FOR
		WASTE	TANK	ISOLATION	WASTE	riguio	STIT.	MONTH	PUMPED	REMAIN	REMAIN	SLUDGE	CAKE	VOLUME	IN-TANK	IN-TANK	THESE
	TANK	MAT'L	INTEGRITY	STATUS	(Kgel)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgal)	(Kgel)	(Kgel)	(Kgel)	UPDATE	PHOTO	VIDEO	CHANGES
								TV TA	NK FARM	STATUS						-	-
	TY-101	NCPLY	ASMD LKR	IS/IP/CCS	118	۰ ا	2	0.0	8.2	2	0	72	48	06/30/99	08/22/89		1
	TY-102		SOUND	IS/IP/CCS	64		12	0.0	6.6	12	5	6	64	06/26/82	07/07/87		1
	TY-103	-	ASMD LKR	IS/IP/CCS	162	٥	20	0.0	11.5	20	16	162	0	07/09/82			
	TY-104		ASMD LKR	IS/IP/CCS	43	آ	4	0.0	0.0	4	0	43	0	06/27/90	11/03/87		ł
	TY-105		ASMD LKR	IS/IP/CCS	231	٥	12	0.0	3.6	12	10	231	o	04/26/82	09/07/89		l
	TY-106	NCPLX	ASMD LKR	IS/IP/CCS	21	٥	3	0.0	0.0	3	0	21	0	06/30/99	08/22/89		
																	<u></u>
_	6 SINGL	E-SHELL	TANKS .	TOTALS:	639	0	53	0.0	29.9	53	31	529	110				
A-13			-					Tr Trab	K FARM	OT A TITLE							
ίω	U-101	NCPLX	ASMD LKR	1S/IP		١.	3		0.0	91VIA		1	0	04/28/82	06/19/79		ſ
	U-101	NCPLX	SOUND	13/11 <sup>-</sup> /PI	25 301	3	29	0.0 2.6	74.0	29	2 19	22 43	258	01/31/01	06/06/89		1
	U-103	NCPLX	SOUND	IS/PI	418	"	33	0.0	98.9	34	28	13	404	05/31/00			(e)
	U-104	NCPLX	ASMD LKR	IS/IP	122		0	0.0	0.0	0	0	79	43	06/30/99	06/10/89		]
	U-105	NCPLX	SOUND	/PI	331	ا     ا	37	0.0	87.5	37	33	32	299	07/31/00			(b)
	U-106	NCPLX	SOUND	/PI	187	ا	29	0.0	39.1	29	17	0	187	12/31/00	07/07/88		(1)
	U-107	DSSF	SOUND	/PI	408	33	92	0.0	0.0	125	115	15	360	12/31/98			"
	U-108	NCPLX	SOUND	/PI	468	24	108	0.0	0.0	132	124	29	415	12/31/98			l
	U-109	NCPLX	SOUND	/PI	399	0	61	0.0	65.9	61	52	35	364	12/31/00			(4)
	U-110	NCPLX	ASMD LKR	IS/PI	186	٥	19	0.0	0.0	18	14	186	0	12/30/84	12/11/84		
	U-111	DSSF	SOUND	/PI	329	0	80	0.0	0.0	80	71	26	303	12/31/98	06/23/88		{
	U-112	NCPLX	ASMD LKR	IS/IP	49	4	4	0.0	0.0	8	4	45	0	02/10/84	08/03/89		i
	U-201	NCPLX	SOUND	IS/IP	5	1	1	0.0	0.0	2	1	4	0	08/15/79	08/08/89		1
	U-202	NCPLX	SOUND	IS/IP	5	1 1	1.	0.0	0.0	2	1	4	0	08/15/79	08/08/89		1
	U-203	NCPLX	SOUND	IS/IP	3	1	0	0.0	0.0	1	1	2	0	08/15/79	06/13/89		1
	U-204	NCPLX	SOUND	IS/IP	3	1	0	0.0	0.0	1	1	2	0	08/15/79	06/13/69		
	16 SING	LE-SHELL	TANKS	TOTALS:	3239	69	496	2.6	365.4	585	483	537	2633				
													***				
	GRAND	TOTAL			33230	1363	3451	10.4	5637.8	4814	3906	11059	20808				

### >

## TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS February 28, 2001

## THESE VOLUMES ARE THE RESULT OF ENGINEERING CALCULATIONS AND MAY NOT AGREE WITH SURFACE LEVEL MEASUREMENTS FOOTNOTES:

Total Waste is calculated as the sum of Sludge and Saltcake plus Supernate. The category "Interim Isolated (II) was changed to Intrusion Prevention (IP) in June 1993. Stabilization information from WHC-SD-RE-TI-178 SST STABILIZATION RECORD, latest revision, or SST Stabilization or Cognizant Engineer

Porosity values are 25% for saltcake and 15% for sludge, per HNF-2978, Rev. 1, "Updated Pumpable Liquid Volume Estimates and Jet Pump Durations for Interim Stabilization of Remaining Single-Shell Tanks," September 1999, with the exception of those tanks which have been interim stabilized and the porosities recalculated.

- (a) S-106 This tank was interim Stabilized on February 1, 2001. DOE concurred on February 12, 2001.
- (b) U-105 Pumping was discontinued July 13, 2000, due to pump failure. Waste levels are being allowed to stabilize, so waste porosities and final waste volumes can then be calculated to determine whether this tank meets interim Stabilization. As of February 28, 2001, waste levels had not yet stabilized.
- (c) S-102 Following information from Cognizant Engineer

Pumping commenced March 16, 1999. Many pumping problems occurred over the following months, and the pump has been replaced several times. Pumping was interrupted again in June 2000, (No pumping since June 2000).

(d) U-109 Following Information from Cognizant Engineer

Pumping began March 11, 2000. Saltcake volume is adjusted to correspond to current waste removal. Remaining volumes based on HNF-2978, Rev. 2.

Pumping was shut down on December 3, 2000, due to jet pump failure. Attempts to restart the pump have been unsuccessful. The tank is currently under observation mode to determine eligibility for interim stabilization with major equipment failure.

(a) U-102 Following information from Cognizant Engineer

Pumping began in this tank on January 20, 2000. Saltcake volume is adjusted to correspond to current weste removal. Remaining volumes are based on HNF-2978, Rev. 2.

Total Waste: 300,9 Kgal Supernate: 0,0 Kgal

Drainable Interstitial Liquid: 29.0 Kgal Pumped this Month: 0.0 Kgal (27 gal)

Total Pumped: 74.0 Kgal

Drainable Liquid Remaining: 29.0 Kgal Pumpable Liquid Remaining: 19.0 Kgal

Skudge: 43.0 Kgal Saltcake: 257.9 Kgal

During February 2001, a total of 340 gal of fluid was removed with 313 gal of water added by pump priming/equipment flushes, for a net removal of 27 gal of wasts. In addition, 1,353 gal of water were used as dilution and 713 gal of water were used for transfer line flushes. In February 2001, only 27 gal of waste was removed from the tank.

# HNP-EP-0182, Rev. 155

#### TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

February 28, 2001

## THESE VOLUMES ARE THE RESULT OF ENGINEERING CALCULATIONS AND MAY NOT AGREE WITH SURFACE LEVEL MEASUREMENT FOOTNOTES:

#### (f) SX-105 Following information from Cognizant Engineer:

Saltwell pumping began August 8, 2000.

Remaining volumes are based on HNF-2978, Rev. 2.

Tank Waste: 485.9 Kgal Supernate: 0.0 Kgal

Drainable Interstial Liquid: 1.9 Kgel Pumped this month: 1.8 Kgel Total Pumped: 15.1 Kgal

Drainable Liquid Remaining: 1.9 Kgal Pumpable Liquid Remaining: -10.1 Kgal (\*)

Siudge: 65.0 Kgel Seltzake: 430.0 Kgel

In February 2001, a total of 2,089 gal of fluid was removed with 269 gal of water added by pump priming and system flushes, for a net removal of 1,820 gal of waste. In addition, 1,961 gal of dilution water and 50 gal of water for transfer lines flushes were used.

(\*) Minus 1,097 gal estimate for PLR because there is more pumpable figuid in the tank than originally estimated. This is due to the fact that approx. 118,000 gal of supernate was in the tank at the start of pumping.

(a) A-101 Following Information from Cognizant Engineer

Pumping began on May 6, 2000. No pumping since August 2000.

Remaining volumes are based on the original estimated volumes in HNF-2978, Rev. 1.

(h) AX-10 Following informtion from Cognizant Engineer

Pumping began July 29, 2000. No pumping since August 2000.

Remaining volumes are based on the original estimated volumes in HNF-2978, Rev. 1.

(i) U-106 Following information from Cognizant Engineer:

Pumping began August 24, 2000. Remaining volumes are based on HNF-2978, Rev. 2.

Pumping rate has fallen below the 0.05 GPM criteria. The pump falled on December 29, 2000. This tank is currently in observation mode to determine sligibility for interim stabilization.

## A-16

## JI) MAY NOT AGREE WITH SIRE

# THESE VOLUMES ARE THE RESULT OF ENGINEERING CALCULATIONS AND MAY NOT AGREE WITH SURFACE LEVEL MEASUREMENTS FOOTNOTES:

TABLE A-6. INVENTORY AND STATUS BY TANK - SINGLE-SHELL TANKS

February 28, 2001

(j) S-109 Following information from Cognizant Engineer:

Pumping began September 23, 2000.

Remaining volumes are based on HNF-2978, Rev. 2.

The pumping rate dropped below .05 gpm and the pump was shut down on January 27, 2001. The tank is now being evaluated to determine if it can be interim stabilized.

(k) SX-103 Following information from Cognizant Engineer:

Pumping began October 26, 2000. Remaining vokumes are based on HNF-2976, Rev. 2.

Total Waste: 524.0 Kgal Supernate: 0.0 Kgal

Drainable interstitial Equid: 37.0 Kgal Pumped this month: 6.0 Kgal Total Pumped: 110 Kgal

Drainable Liquid Remaining: 37.0 Kgal Pumpable Liquid Remaining: 22.0 Kal

Sludge: 115.0 Kgal Saltcake: 409.0 Kgal

In February 2001, a total of 6,361gal of fluid was removed with a total of 365 gal of water added by pump priming/equipment flushes, for a net removal of 5,996 gal of water. In addition, 7,088 gal of water were used as dilution and 3,727 gal of water were used for transfer line flushes.

(I) SX-101 Following information from Cognizant Engineer:

Pumping begen November 22, 2000

Remaining volumes are based on HNF-2978, Rev 2. Saltcake volume is adjusted to correspond to current waste removal.

Total Waste: 428.8 Kgal Supernate: 0.0 Kgal

Orainable Interstitial: 92.8 Kgal Pumped this Month: 6.9 Kgal Total Pumped: 19.2 Kgal

Drainable Liquid Remaining: 92.8 Kgal Pumpable Liquid Remaining: 86.7 Kgal

Słudge: 0.0 Kgai Saltcake: 428.8 Kgai

No pumping since December 2000.

# APPENDIX B PERFORMANCE SUMMARY

# TABLE B-1. SUMMARY OF WASTE TRANSACTIONS IN THE DOUBLE-SHELL TANK (DST) SYSTEM February 28, 2001

### All volumes in Kilo-Gallons

- The DST system received waste additions from SST pumping, Tank Farms, NaOH, campaign 01-01,& 151-AZ in February.
- There was a net change of +81,000 gallons in the DST system for February 2001.
- The total DST inventory as of February 28, 2001 was 21.207 million gallons.
- There were 0 Kgals of Saltwell Liquid (SWL) pumped to the East Area DSTs (101-AN) in February.
- There were ~20 Kgals of SWL pumped to the West Area DSTs (102-SY) in February.
- The SWL numbers are preliminary and are subject to change once cognizant engineers do a validation, the volumes reported contain actual waste volume plus any water added for dilution and transfer line flushes.
- There were ~72,000 gallons of caustic (NaOH) (four transfers), added to Tank 102-AY in February,
- ~1000 gallons of water was used to flush the waste transfer system after the caustic additions.
- The Cold Run (training and testing) for evaporator 242A campaign 01-01 commenced in February, ~2,000 gallons of water was added to Tank 102-AW in conjunction with the Cold Run. Up to 120,000 gallons of water can be expected to be received into Tank 102-AW during campaign 01-01 Cold Run activities.
- The solids volumes in Tanks 101-AY and 102-AY were adjusted in February. The driver for these changes was new "Tank Farm Sludge Level Readings" taken Jan. 19, 2001. BBIM cog. Engineers reviewed the data and concurred with the change.
- SST 106-S was deemed Interim Stabilized in February. The tank has met stabilization criteria and documentation has been issued. Tank S-106 final waste volume inventories (post stabilization) are: ~429 Kgals of Saltcake with ~26 Kgals of Interstitial Liquid, for a total waste volume of ~455 Kgals.

FACIL	TY GENERATIONS	OTHER GAINS ASS		OTHER LOSSES AS	SOCIATED WITH
SWL (West)	+20 Kgal (2SY)	SLURRY	+0 Kgal	SLURRY	-4 Kgal
Caustic (NaOH)	+73 Kgal (2AY)	CONDENSATE	+7 Kgal	CONDENSATE	-4 Kgal
Tank Farms	+5 Kgal (2AN)	INSTRUMENTATION	+0 Kgal	INSTRUMENTATION	-13 Kgal
Evap, Training	+2 Kgal (2AW)	UNKNOWN	+0 Kgal	UNKNOWN	-5 Kgal
1(0)7		TOTAL=	+7 Kgal	TOTAL=	-26 Kgal

					i Bis	
	ACTUAL DST WASTE RECEIPTS	PROJECTED D8T WASTE RECEIPTS (1)	MISC. DST CHANGES (+/-)	PROJECTED WVR (1)	NET DST CHANGE	TOTAL DST VOLUME
OCT00	222	155	-24	0	198	20653
NOV00	261	262	-14	0	247	20900
DEC00	139	300	-1	0	138	21038
JAN01	113	397	-25	0	88	21126
FEB01	100	303	-19	0	81	21207
MAR01		-283		-684		
APR01		321		0		
MAY01		302		0		
JUN01		334		_ 0		
JUL01		296		0		
AUG01		289		0		
SEP01		282		0		

(1): The "PROJECTED DST WASTE RECEIPTS" and "WVR" numbers were updated in November 2000, the projected volumes will be updated as new and/or more accurate information is obtained. The projected volumes reported are the most current available, as supplied by cognizant engineers.

22.50	Everyettatos Wasia Volumas P	Caratina
Campaign 94-1	(04/15/94 - 06/13/94)	-2417
Campaign 94-2	(09/22/94 - 11/18/94)	-2787
Campaign 95-1	(06/09/95 - 07/26/95)	-2161
Campaign 96-1	(05/07/96 - 05/25/96)	-1117
Campaign 97-1	(03/24/97 - 04/02/97)	-351
Campaign 97-2	(09/16/97 - 09/30/97)	-653
Campaign 99-1	(07/24/99 - 08/15/99)	-818
Campaign 00-1	(04/20/00 - 05/05/00)	-682
	luction (WVR) since restart on 4/15/94	-10986




Figure B-1. Comparison of Projected Versus Actual Waste Volumes for Hanford Facilities

This page intentionally left blank

# APPENDIX C

# DOUBLE-SHELL TANK WASTE TYPE AND SPACE ALLOCATION

# Table C-1. Double-Shell Tank Waste Inventory - February 28, 2001

10/ALS \$1200	TAL AVAILABLE DET SPACE
ALOL TOPE	MON NON

	241-87-103	201-47-102	241-87-101	241-AZ-102	241-AZ-101	241-44-102	241-AY-101	241-494-108	241-494-106	341-AW-104	241-44-103	241-444-102	241-AW-101	241-45-108	241-4-19	24147-108	341-44-105	261-44-104	241-45-103	21.4-12	241-AP-101	241-44-107	241-44-108	241,44105	241-741-04	241-44-103	2414102	241-44-101	NAME	TANK	
	8	8	8	NCAW	NCAM	¥	8	DSSF	NORW	Z	NCM*	¥	#88C	¥	8	8		8	8	ŝ	2000	8	8	0447	Dest	255	8	70	TYPE	WASTE	
71 <b>217</b>	742	2	970	3	224	245	É	75	ŝ	316	8	Į	1128	37	8	8	134	1104	282	Ö	1111	1040	¥	121	Ď	8	i de	127	INVENTORY (1)	TOTAL	
	378	5	387	<b>3</b> 1	172	472	8	\$	191	8	ž	ş	761	37	8	8	546	ŝ	ž	Ó	1111	28	2	2	8	ŧ	*	12	SUPERNATE	TOTAL	
	3	2	ŧ	ŝ	8	173	76	238	¥	ភ	¥	Ħ	376	•	•	•	8	•	•	0	0	247	7	ŧ	ŧ	<b>6</b> 7	8	0	\$0UD\$ (3)	TOTAL	
	38	0	25	0	0	•	0	228	9	걸	4	8	375	•	ø		8		•	•	٥	247	₹	ŧ	ŧ	45	8		BALTCAKE (2)		
2 To 188	82	•	2)	. 0	0	Ð	0	8	0	2	ನ	•	2	0	0	•	Ħ		•		٥	5	•	Ŕ	12	ī	ĸ	0	LIQUID	SALTCAKE	
	0	2		106	23	173	- 62	0	¥	•	31	0	0	- 0	٥	•	•	•	•	•	. 0		•		•	•	_	0	SLUDGE (2)		
0.1	ø	=	0	<b>=</b>	•	×	=	•	¥	۰	3	0	0	0	0	•	•	•	•	۰	٥	0	•	•	۰	9	۰	0	LIQUID	SLUDGE	
1000	388	Ē	170		56	336	796	\$3	716	134	R	272	14	1103	157	518	•	ĸ	**	6	23	100	102	ត	E	Ť	\$	916	TANK SPACE	CARONO	REMAINING

NOTE: All Volumes
(1) Total inventor
(2) Saltcake Inch
(3) Yotal Solids ee in Kilo-Galione (Kgale); Tanks 101-AY and 102-AY solids updats in Fabruary tory = (Total Supernate + Total Solids) cludes Saltcaks Liquids; Sludge includes Sludge Liquid s = (Saltcaks + Sludge)

		KENAMING BYACE
	DET SLUDGE / SA	
	Dat solue (No Light)	
	AGING SUPERING E AWIT	900000000000000000000000000000000000000
COMPANIE ATEN BLOSDIATE (CD).	COMPANIA	
	CONCENTRATED	AY-101= 796
	STURRY (DESCRIPTION	
VIE (DANC) - 4408	DILUTE SUPERNATE (DNDC) -	AW-103# 632
GRAND TOTALS		157
TOTAL BLUDGE / BALTCAKE LIQUIDY	(0)	AP-106*
SY-100= 621	AW-103=	AP-104-
\$Y-107		AP-100e
<b>67-101=</b> 21		AP-101# 26
AZ-102** 16	WF-108-	A4+100= 1102
AZ-1018	A+107*	W+101s
AY-102**	AV-100m	NON-ALLOCATED SPACE
AY-101= 11	AN-106-	
AW-100= 60	AN-104- 112	TOTAL=
WW-106=	** 188* 114	
AVX-1048		AVF-101=
DST SCUDGE / SALTCARE LIQUID		21.
		OFF.
		100
		WATCH LIST SPACE
	TOTAL DESCRES	
TOTAL SOLDS 187	AVX-108m 499	TOTAL 483
TOTAL AWA 1788	AW-101s 751	SY-101= 170
AZ-(102= 891)		AZ-102*
A2-101m	AP-1012	AZ-101=
AGING SUPERNATE (AW)		AP 102*
TOYAL BOLLOS		- 107m
(O)ALCCCCC	ני שטרפתושיו בו ואינואפרטים	スののシスプンがどのアメンカ
57-155s		
	Sont Contrac	101AC-
	0.0000000000000000000000000000000000000	
		200 100 E
NP-1000	AW-104=	Z7Z
AP-104= 1106	AW-100= 146	AA-108= 1103
AP-103- 282	ANY-102m BSB	OPERATIONAL SPACE
AN-107= 783	AP-108-	
21	## NOT# 224	CHANGE
##-102°	CILUTE SUPERNATE (DN)	CUOT TANK SPACE 10089
CONTINUE OF EXPANSION (DOCTOR)		
からには まくれつ きこうりきとうけん マスクラン		CONTRACTOR OF
memory Calculation by France Type:		TANK SPACE CHANGE
		distribution of the same
		(3) York Solids = (Selective + Studge)

Table C-2. Double-Shell Tank Waste Inventory - February 28, 2001

TOTAL AVAILABLE USABLE A	S OF FEBRUA	KY 28, 2001 =	19089 KGALB
WATCH LIST TANK SPACE:	TANK	WASTE TYPE	AVAILABLE SPACE
Inusable DST Heedspace - Due to Special Restrictions	AN-103		184 KGALS
Paced on the Tanks, as Stated in the "Wyden Bill"	AN-104		88 KGALS
	AN-105		12 KGALS
	AW-101		14 KGALS
	\$Y-103	********************************	398 KGALS
		TOTAL*	698 KGALB
	,	AVAILABLE TANK SPAC	
	MiM	IUS WATCH LIST SPAC	CE= -696 KGALS 8383 KGALS
TOTAL AVAILABLE SPACE AFTER	WATCH LIST	BPACE DEDUCTIONS=	
RESTRICTED TANK SPACE:	TANK	WASTE TYPE	AVAILABLE SPACE
DST Headspace Available to Store Only Specific Wast	Typ AN-102	CC	85 KGALS
	AN-107		100 KGALS
	AP-102	CP	52 KGALS
	AZ-101		56 KGALS
•	AZ-102		0 KGALS
	SY-101		170 KGALS
•	. •	TOTAL=	443 KGALB
AVAILABLE SPACE AFTER	WATCH LIST S	SPACE DEDUCTIONS=	9393 KGALS
MANAGE OF MOSTA (SI)		S RESTRICED SPACE	
TOTAL AVAILABLE SPACE APTER I			8930 KGALB
OPERATIONAL TANK SPACE	TANK	WASTE TYPE	AVAILABLE SPACE
OST Headspace Available For Fecility Generated	AP-108	DN	1103 KGALS
Vaste and 242-A Evaporator Operations	AW-102	DN	272 KGALS
	AW-105	NCRW	714 KGALS
	AW-106	DSSF	402 KGALS
	SY-102	DC	238 KGALS
		TOTAL=	2729 KGAL8
AVAILABLE SPACE AFTER	RESTRICTED	SPACE DEDUCTIONS	8930 KGALS
		OPERATIONAL SPACE	
TOTAL AVAILABLE SPACE AFTER (			
NON-ALLOCATED TANK SPACE	TANK	WASTE TYPE	AVAILABLE SPACE
Ion-Alloctated DST Headspace	AN-101	DN	916 KGALS
	AN-106		1102 KGALS
	AP-101	DSSF	26 KGALS
	AP-103		858 KGALS
	AP-104	-	32 KGALS
	AP-105	<b>-</b>	6 KGALS
	AP-106		518 KGALS
	AP-107		157 KGALS
	AW-103		632 KGALS
	AW-104		824 KGALS
	AY-101		795 KGALS
	AY-102	= -	335 KGALS
το	TAL NON-ALL	CATED TANK SPACE	= 8201 KGAL#
FLANCE	RGENCY TANK	SPACE	-1140 KGAL8
		· · · ·	
	OF HEW RETUR	IN SPACE	-1140 KGAL8




Figure C-1. Total Double-Shell Tank Inventory

# APPENDIX D

WASTE TANK SURVEILLANCE MONITORING TABLES

# TABLE D-1. TEMPERATURE MONITORING IN WATCH LIST TANKS (Sheet 1 of 2) February 28, 2001

These tanks have been identified as Watch List Tanks in accordance with Public Law 101-510, Section 3137, "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," (1990), because they "... may have a serious potential for release of high-level waste due to uncontrolled increases in temperature or presssure."

All Watch List tanks are reviewed for increasing temperature trends. Temperatures in these tanks are monitored by the Tank Monitor And Control System (TMACS), unless indicated otherwise.

Temperatures are taken in the waste unless in-waste thermocouples are out of service. Temperatures below are the highest temperatures recorded in these tanks during this month.

Temperatures in Degrees F.

		HYDROGEN (F	LAMMABLE GAS)								
	Single-Sh	ell Tanks	Double-Shell Tanks								
		Officially Added to		Off	icially Added to						
Tank No.	Temp.	Watch List	Tank No.	Temp.	Watch List						
A-101	143	1/91	AN-103	103	1/91						
AX-101	128	1/91	AN-104	105	1/91						
AX-103	106	1/91	AN-105	101	1/91						
S-102	100	1/91	AW-101	98	6/93						
S-111	89	1/91	SY-103	95	1/91						
S-112	83	1/91	& DSTe								
SX-101	127	1/91									
SX-102	139	1/91	ŀ								
SX-103	154	1/91									
SX-104	137	1/91									
SX-105	158	1/91									
SX-106	98	1/91									
SX-109 (1)	133	1/91		19 Single-She	ll Tanks						
T-110	63	1/91	•	5 Double-She	II Tanks						
U-103	87	1/91		24 Tanks on \	Watch List						
U-105	87	1/91	ļ								
U-107	78	12/93									
U-108	86	1/92	1								
U-109	85	1/91									
19 SST:											

All tanks were removed from the Ferrocyanide Watch List and 18 tanks from the Organics Watch List. Tank C-106 was removed from the High Heat Load Watch List on December 16, 1999. The remaining two tanks (C-102 and C-103) were removed from the Organics Watch List in August 2000. DST SY-101 was removed from the Hydrogen Watch list on January 11, 2001.

# TABLE D-1. TEMPERATURE MONITORING IN WATCH LIST TANKS (sheet 2 of 2)

# Notes:

# Unreviewed Safety Ouestion (USO):

When a USQ is declared, special controls are required, and work in the tanks is limited. There are currently no USQs on any tanks.

## Hydrogen/Flammable Gas:

These tanks are suspected of having a significant potential for hydrogen/flammable gas generation, entrapment, and episodic release. The USQ associated with these tanks was closed in September 1998. Twenty-four tanks (19 SST and 5 DST) remain on the Hydrogen Watch List.

### High Heat:

These tanks contain heat generating strontium-rich sludge and require drainable liquid to be maintained in the tank to promote cooling. There are currently nine tanks on the High Heat Load List but no tanks on the High Heat Load Watch List.

# Active ventilation:

There are 15 single-shell tanks on active ventilation (seven are on the Watch List as indicated by an asterisk):

C-105	SX-107
C-106 (2)	SX-108
SX-101 *	SX-109 * (1)
SX-102 *	SX-110
SX-103 *	SX-111
SX-104 *	SX-112
SX-105 *	SX-114
SX-106 *	

### Footnotes:

- (1) Tank SX-109 is on the Hydrogen Watch List as it has the potential for flammable gas accumulation only because other SX tanks vent through it.
- (2) Tank C-106 was removed from the High Heat Load Watch List on December 16, 1999.

# TABLE D-2. TEMPERATURE MONITORING IN NON-WATCH LIST TANKS February 28, 2001

# SINGLE-SHELL TANKS WITH HIGH HEAT LOADS (>26,000 Btu/hr)

Nine tanks have high heat loads for which temperature surveillance requirements are established by HNF-SD-WM-TSR-006, Rev 1, Tank Waste Remediation System Technical Safety Requirements, December 1999. In an analysis, WHC-SD-WM-SARR-010, Rev 1, Heat Removal Characteristics of Waste Storage Tanks, Kummerer, 1995, it was estimated that nine tanks have heat sources >26,000 Btu/hr, which is the new parameter for determining high heat load tanks. See also document HNF-SD-WM-BIO-001, Rev 1, Tank Waste Remediation System Basis for Interim Operation, Noorani, 1998.

Temperatures in these tanks did not exceed the Technical Safety Requirements (TSR) for this month, and are monitor and Control System (TMACS), unless indicated otherwise. All high heat load tanks are on active ventilation.

Tank No.	Temperatu	re (F.)
C-106 (1)	56	(Riser #8)
SX-103	154	
SX-107	162	
SX-108	179	
SX-109 (2)	133	
SX-110	161	
SX-111	181	
SX-112	145	
SX-114	173	
D TOCK !		

### Notes:

- (1) C-106 was removed from the High Heat Load Watch List on December 16, 1999. The final thermal analysis report, RPP-6463, Rev. 0, "Thermal Analysis for Tanks 241-AY-102 and C-106," was issued August 9, 2000. The report concluded that the best estimate heat load for C-106 is between 7,000 and 11,000 Btu/hr. Although it no longer meets the criteria for a high heat load tank, it will take an AB change to revise the temperature control limits and monitoring frequency. The AB Amendment request is pending review by ORP.
- (2) SX-109 is on the Hydrogen Watch List as it has the potential for flammable gas accumulation only because the other SX tanks vent through it.

# SINGLE-SHELL TANKS WITH LOW HEAT LOADS (<26,000 Btu/hr)

There are 114 low heat load non-watch list tanks. Temperatures in tanks connected to TMACS are monitored by TMACS; temperatures in those tanks not yet connected to TMACS are manually taken semiannually in January and July. Temperatures obtained semiannually have been within historical ranges for the applicable tank.

No temperatures have been obtained for several years in the tanks listed below. Most of these tanks have no thermocouple tree.

Tank No.		<u>Tank No.</u>
BX-104		TX-101
BY-102		TX-110
BY-109		TX-114
C-204		TX-116
SX-115		TX-117
T-102		U-104
T-105	D-4	

# TABLE D-3. ADDITIONS/DELETIONS TO WATCH LISTS BY YEAR February 28, 2001

Added/Deleted dates may differ from dates that tanks were officially added to the Watch Lists. (See Table A-1).

							***		بنستية.	
		cyanide	Hydrogen	(	Organics	High Heet			DST	10000000000000
TAX COURSE AND COMPANIES IN PARCE AND SOLD		T-107	72			1	100	- T		<b>52</b>
Added 2/91 (revision to Original List) Total - December 31, 1991		1-107	**							· · · · · · · · · · · · · · · · · · ·
Added 6/92		***************************************	1 AW-101	ores announced				48	1	1 54
Total - December 31, 1992 Added 3/93				1	U-111			1		***********
Deleted 7/93	-4	(BX-110) (BX-111)		1				-4		
1	1	(BY-101)								
Added 12/93		(T-101)	1 (U-107)					o		
Total - Cecamber 31, 1993	<b>100</b>		4.			1		<b></b>		5.1
Added 2/94 Added 5/94				10	T-111 D A-101			4		
Added 5/44					AX-102 C-102					
	Į.				S-111					
i					\$X-103 TY-104			ļ		
	l				U-103					
	l			1	U-105 U-203	İ				
	١.,	(BX-102)			U-204			-2		
Deleted 11/94		(BX-106)							100000000000	**************
Total: Cecember (1): 1986		(C-108)				1				5.8
Deleted 6/96	~	(C-109)								
	İ	(C-111) (C-112)				İ				
Deleted 9/96	-14	(BY-103)						-12		
	1	(BY-104) (BY-105)								İ
		(BY-106) (BY-107)								
	1	(BY-108)	·							
		(BY-110) (BY-111)				ļ				
	İ	(BY-112)								
		(T-107) (TX-118)							ŀ	
		(TY-101) (TY-103)		1			33			j
		(TY-104)		1.						
Deleted 12/98				-1	B (A-101) (AX-102	1		-10		
					(B-103)					
					(S-102) (S-111)					
	ŀ				(SX-103) (SX-106)				l	
					(T-111)				l	
·	l		j		(TX-105) (TX-118)				1	1
					(TY-104)					l
					(U-103) (U-105)					1
			1	-	(U-106) (U-107)				1	1
				1	(U-111)					
}					(U-203) (U-204)					
Total - December \$1, 1985	0		25		1			212		2
Deleted 12/99				-	1 (C-102)	-1 (C-108	1	-1		<del>                                     </del>
Deleted 08/00				<b>-</b>			1	-1		
Deleted 01/01			-1 (SY-10)		•	0		18	-	
Total - February 28, 2001	0						3 13	0.0000000	4 1000 00000.	

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 1 of 6) February 28, 2001

The following table indicates whether Single-Shell tank monitoring was in compliance with the requirements as specified in the applicable documents as of the last day of the applicable month:

## NOTE:

All Watch List and High Heat tank temperature monitoring is in compliance. (4)

All Dome Elevation Survey monitoring is in compliance

Psychrometrics monitoring is on "as needed" basis (2).

Drywell monitoring no longer required (5). In-tank photos/videos are taken "as needed"

LEGEND:	
(Shaded)	= in compliance with all applicable documentation
N/C	<ul> <li>noncompliance with applicable documentation</li> </ul>
0/5	= Out of Service
Neutron	<ul> <li>LOW readings taken by Neutron probe</li> </ul>
POP	= Plant Operating Procedure, TO-040-650
MT/FIC/	= Surface level measurement devices
ENRAF	
OSD	<ul> <li>Operating Spec. Doc., OST-T-151-00013, 00030, 00031</li> </ul>
N/A	= Not applicable (not monitored, or no monitoring schedule)
None	= Applicable equipment not installed
FSAR/TSR	= Final Safety Analysis Report/Technical Safety
	Requirements

	Tenk	Category	Temperature	Primary Leak	Sur	face Level Read	lings (1)	LOW Readings
Tank	Watch	High	Readings	Detection		(OSD)		(OSD)(5,7)
Number	List	Heat	(4)	Source (5)	MT	FIC	ENRAF	Neutron
A-101	X			LOW	Hora	and the state of		
A-102				None	1230		Nove	None
A-103				LOW	1.50	None		
A-104				None		None		None
A-105				None		nien)	Nore	None
A-106				None		None		None
AX-101	× ×			LOW		None		191
AX-102				None	1 days			Pitone
AX-103	X			None	liana.	Bione		None
AX-104				None	None	None		None
B-101				None	555	None		None
B-102				ENRAF		None		None
B-103				None		None		0/6
B-104				LOW	i i i i i	None		
B-105				LOW	0.00	None		
B-106				ENRAF	tere.	None		None
B-107				None	100	None		None
B-108				None	None	None		None
B-109				None	None	None		None
B-110				LOW	firete	None		(12)
B-111				LOW	tions.	Name		
3-112				ENRAF	i i i i i i i i i i i i i i i i i i i	None		None
3-201				ENRAF	Alberta	Norse		None
B-202				ENRAF	Books	None		None
B-203				ENRAF		None		None
B-204				ENRAF	Sec	Listo .		None
3X-101				ENRAF	.icre			None
BX-102				None		None.		fenere
BX-103				ENRAF		None		Svore
BX-104			Noise	ENRAF	No.	a Company		None
3X-105				None	Name	None		None
BX-108				ENRAF	None	Here		House
BX-107				ENRAF	Nors	None		None

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 2 of 6)

	Tank (	Category	Temperature	Primary Leak	Surfa	ce Level Readir	ngs (1)	LOW Readings		
Tank	Watch	High	Readings	Detection		(OSD)				
Number	List	Heat	(4)	Source (5)	MI	FIC	ENRAF	Neutron		
BX-108				None	Note					
BX-109				None						
BX-110				None	100					
BX-111				LOW		(Media)				
BX-112				ENRAF	Acces.	Section		2.00		
BY-101				LOW						
BY-102				LOW	. Some	Mone				
BY-103 BY-104				LOW	Nexa	0.000				
BY-105	2000			LOW		None				
BY-106				LOW		None				
BY-107				LOW		trens	No.			
BY-108		***************************************		None		State		1555		
BY-109				LOW	. Sione	0.8				
BY-110				LOW	Second					
BY-111				LOW						
BY-112				LOW		a de la companya del companya de la companya del companya de la co				
C-101				None						
C-102 (10)				None	line.					
C-103 (10)				ENRAF						
C-104				None	1,000					
C-105				<u>Nana</u>	TV.					
C-106 (3)		1		ENRAF		Meso				
C-107				ENRAF	Xe.e					
C-106				None						
C-109 C-110		6		None		Secret Secret		A CANCEL		
C-111				None				300000000000000000000000000000000000000		
C-112	E 1990 E 1990			None	None		er foreste en mande de ser en en en en en en en en en en en en en			
C-201				None						
C-202				None				7-5-6		
C-203				None		9000	9800	1000		
C-204				None						
S-101				ENRAF						
S-102				LOW	300					
S-103				ENRAF	None	and the second				
S-104				row	None					
S-105				LÓW	Ricera					
S-108				LOW	None					
8-107				ENRAF	No.:			Late		
S-108				LOW	None	1.070				
S-109 S-110				LOW	North North	None Score				
S-111				ENRAF						
S-112				LOW						
8X-101	X			LOW						
SX-102				LOW	, Long					
8X-103	X			LOW	None					
SX-104	×			LOW						
SX-105		<b>200</b>	1.00	LOW	17-9-4-18			(2/8 (13)		
SX-106	1			LOW	No.					
SX-107				None						
SX-108		7		None				None		

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 3 of 6)

	Tank (	Category	Temperature	Primary Leak	Surf	sce Level Readi	ings (1)	LOW Readings	
Tenk	Watch	High	Readings	Detection		(OSD)		(OSD)(5,7)	
Number	List	Heat	(4)	Source (5)	МТ	FIC	ENRAF	Neutron	
SX-109		X		None	None	None		Hone	
SX-110		Х		None	None	None		Nana	
SX-111		2.		None	None	None		lyane .	
SX-112		×		None	None	None		Nore	
SX-113				None		None		None	
SX-114				None	lione.	More		None	
SX-115			Pione .	None	fione	None		Blene	
T-101				None	Roca	Blone		ACTO	
T-102			None	ENRAF	None	None		None	
T-103				None	hinne	Acid		None	
T-104				LOW	None	None			
T-105			None	None	Need	None		None	
T-106	_			None	None	None		None	
T-107	_			ENRAF	None	None		tione Since	
T-108				ENRAF	None	None		Hors	
T-109				None	***************************************				
T-110	×			LOW	None	bione			
T-111				ENRAF	None	None		Nene	
T-112	_				NOM	None			
T-201	_			MT		Bione	None	None	
T-202				MT		None	None	None Nete	
T-203				None MT		None	None	None	
T-204				ENRAF	None	~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	n de la constant	None	
TX-101			None	LOW	None	None			
TX-102				None	fiore	Blone Note		None	
TX-103 TX-104				None	None	None		Refu	
				None		None		None (B)	
TX-106 TX-106				LOW	No.	biore			
TX-100				None	tions	1000		None	
TX-107				None	Social	None		None	
				LOW	None	None			
TX-109 TX-110				LOW	None	None			
			None	LOW	tions	Bone			
TX-111 TX-112				LOW	None	None			
TX-112				LOW	None	None			
			None	LOW	None	Nerve			
TX-114 TX-115				LOW	Page	None			
TX-116			None	None	None	None		Nene	
			None	LOW	None	None		78718	
TX-117			2 0000 000 marks (000000	LOW					
TX-118					None None	None None		1	
TY-101				None	None	None		None None	
TY-102				LOW	None	None			
TY-103									
TY-104				ENRAF	None None	None		Hone	
TY-105				None		None		None	
TY-106				None	None	None		Nerte	
U-101	_			MT		None	None	Nore	
U-102				LOW	None	Norm			
U-103	×			LOW	None	Nors			
U-104			None	None		None	None	None	
U-106	X			LOW	None	None			
U-106				LOW	None	Horse			

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS 149 TANKS (Sheet 4 of 6)

	Tank Category		Temperature	Primary Leak	Surl	LOW Readings		
Tank	Watch	High	Readings (4)	Detection Source (5)	МП	(OSD)(5,7)		
Number	List	Heat				FIC	ENRAF	1460.011
J-107				ENRAF	None	None		
U-108				LOW		No.		
U-109				LOW	and the second	Sea.		
J-110				None	Norm	Here		
J-111				row		No. of the second		
J-112				None		- Core	No.	
J-201				MT		(		
J-202				MT		None	Nore	, Carre
U-203				None	None	Heat		
J-204				ENRAF	None	None		Berra
Catch Tanks a	nd Special Su	nvelllence Fer	ilities					
A-302-A	N/A	N/A	27/4		1 E 1 E 1 E 1 E 1 E 1 E 1 E 1 E 1 E 1 E	i Koro		
A-302-A A-302-B	14.4	777		(8)		None	el com	
R-311		N/A	<b>N</b>	•	Here			************
AX-152		e li		•		New		
AZ-162		NIA		(8)	Sec.			a de la composition della composition della comp
AZ-161 AZ-164		1/2			6 60 10 10 10 10 10 10 10 10 10 10 10 10 10	None		
AZ-104 BX-TK/SMP		17		(6)		None		
	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		777	(6)		None	None	
A-244 TK/8MP		17	SIA	100		No.		2070
AR-204	777		8/6		Nere	None	None	
A-417 A-350	*****			(6)		None	Nices	i de la companya de la companya de la companya de la companya de la companya de la companya de la companya de
R-360 CR-003			3/4	6	Name	None	Notes	More
				18		Rope	100	i i i i i i i i i i i i i i i i i i i
Vent Sta. 244-S TK/SMP	C.A.			[6	Mone	None	e e e e e e e e e e e e e e e e e e e	Siore
	317		1. A			V TO		
S-302	277		77.5	(6)	100	Piges		
S-304	300000003030000000000000000000000000000		10/4	**************************************		15000	Notes	
TX-244 TK/SMP	***************************************					fore	None	None
TX-302-B			N/A	(6)		hone		
TX-302-C	aya.	U/A	C		1	None		1,000
U-301-B		1/.				tions		\$ 50 TM
UX-302-A	W.A.	N/A		(4) (6)		None	None	liere.
5-141	NIA	N/A N/A	NA UA		0/1	None	None	
S-142		200000000000000000000000000000000000000	000000000000000000000000000000000000000		N/C: 0	N/C: 0	N/C: 0	N/C: O
Totals: 149 tanks	Hydrogen Watch List Tanks	9 High Heat Tenks (non- Watch List)	N/C: 0		, , , , , , , , , , , , , , , , , , ,			

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS -149 TANKS (Sheet 5 of 6)

### Footnotes:

1. All SSTs have either manual tape, FIC, or ENRAF surface level measuring devices. Some also have zip cords.

ENRAF gauges are being installed to replace FICs (or sometimes manual tapes). The ENRAF gauges are being connected to TMACS, but many are currently being read manually from the field. See Table D-6 for list of ENRAF installations.

2. High heat tanks have active exhausters; psychrometrics can be taken in the high heat tanks. Psychrometric readings are not required by OSD, but can be taken on an "as needed" basis.

Psychrometric readings are taken annually in SX-farm.

- 3. Tank C-106 was removed from the High Heat Load Watch List on December 16, 1999.
- 4. Temperature readings may be regulated by OSD, POP, or FSAR (FSAR only regulates high heat load tanks).

  Temperatures cannot be obtained in 13 low heat load tanks (see Table D-2). The OSD does not require readings or repair of out-of-service thermocouples for the low heat load (<26,000 Btu/n) tanks. However, the POP requires that attempts are to be made semiannually in January and July to obtain readings for these tanks.

Temperatures in some tanks cannot be taken in the waste because the waste level is lower than the lowest thermocouple in these trees.

Temperatures for many tanks are monitored continuously by TMACS; see Table D-7, TMACS Monitoring Status.

5. Document OSD-T-151-00031, "Operating Specifications for Tank Farm Leak Detection," Rev. D-2, December 7, 2000, requires that single-shell tanks with the surface level measurement device contacting liquid, partial liquid, or floating crust surface, will be monitored for leak detection on a daily basis. Tanks with a solid surface will be monitored for leak detection on a weekly basis by taking neutron scan data from a Liquid Observation Well (LOW), if an LOW is present. Tanks with a solid surface but without LOWs will not be monitored for leak detection until an LOW is installed. The OSD specifies what leak detection methods are to be used for each tank, and the requirements if the readings are not taken on the required frequency or if equipment is out of service.

This OSD revision does not require drywell surveys to be taken; drywell scans will only be taken by special request, since any scans would have to be subcontracted. The contractor no longer has drywell scanning equipment.

6. Leak detection for the catch tanks is performed by monitoring for the buildup of liquid in the secondary containment (for most tanks with secondary containment) or for decrease in the liquid level for those tanks without secondary containment or Catch tank 241-S-302 is monitored for intrusions only, and is not subject to leak detection monitoring requirements until liquid is present above the intrusion level.

Weight Factor is the surface level measuring device currently used in A-417, A-350, 244-A Tank/Sump, and 244-S Tank/Sump. Double-Shell Receiver Tank (DCRT) CR-003 is inactive and measured in gallons. 204-AR is also measured in gallons.

7. Document SD-WM-TI-605, REV. 0, dated January 1994, describes the rationale for Liquid Observation Well (LOW) installation priority. This priority is based on tank leak status, tank surface condition, and tank stabilization status. Also included is a listing of tanks with the waste level being below two feet, which have no priority assigned because no effort will be made to install LOWs in the near future. LOW probes are unable to accurately monitor interstitial liquid levels less than two feet high.

# TABLE D-4. SINGLE-SHELL TANKS MONITORING COMPLIANCE STATUS - 149 TANKS (Sheet 6 of 6)

Tanks which will not receive LOWs:

A-102	BX-101	C-201	T-106
A-104	BX-103	C-202	T-108
A-105	BX-105	C-203	T-109
AX-102	BX-106	C-204	TX-107
AX-104	BX-108	SX-110	TY-102
B-102	C-108	SX-113	TY-104
B-103	C-109	SX-115	TY-106
B-112	C-111	T-102	<b>U-101</b>
		T-103	U-112

Total - 34 Tanks

- 8. Tank TX-105 the LOW was in riser 8; the riser has been removed and the LOW has not been monitored since January 1987. Liquid levels are being taken in riser 9 by ENRAF and recorded in TMACS.
- 9. Tank AX-101 LOW readings are taken by gamma sensors.
- 10. Tanks C-102 and C-103 were removed from the Organics Salts Watch List on August 23, 2000
- 11. Tank SX-105 LOW scan not taken for week ending August 28, 2000. LOW is primary leak detection device; ENRAF is backup and monitored daily in TMACS. LOW has failed structurally, and will be replaced. Work Package 2H0005040. Fabrication shop has received materials: awaiting scheduling. (Tank is currently being saltwell pumped).
- 12. Tank B-110 LOW scan not taken for week ending October 9, 2000. LOW is primary leak detection device; no stated backup, so device must be repaired in 14 days or an alternative device used to obtain a valid reading before an OSD violation occurs. Discrepancy Report 00-884 (Rev 3) issued February 8, 2001. The LOW was not repaired and a valid scan obtained by February 7, 2001. The repair provisions in OSD-31 were exceeded and an OSD violation occurred. (For intrusions, an ENRAF gauge was monitored daily in TMACS). A new LOW was installed on February 21, and a scan taken on February 22, 2001, with good results. Discrepancy Report closed.

# TABLE D-5. DOUBLE-SHELL TANKS MONITORING COMPLIANCE STATUS 28 TANKS (Sheet 1 of 2) February 28, 2001

The following table indicates whether Double-Shell tank monitoring was in compliance with the requirements as specified in the applicable documents as of the last day of the applicable month.

### NOTE:

Dome Elevation Surveys are not required for DSTs.

Psychrometrics and in-tank photos/videos are taken "as needed" (2)

LEGEND: (Sheded) N/C FIC/ENRAF	<ul> <li>In compliance with all applicable documentation</li> <li>Noncompliance with applicable documentation</li> <li>Surface level measurement devices</li> </ul>
M.T. OSD None	= OSD-T-151-0007, OSD-T-151-0003? = no M.T., FIC or ENRAF installed
O/S W.F.	= Out of Service = Weight Factor
N/A Rad.	<ul> <li>Not Applicable (not monitored or no monitoring schedule)</li> <li>Radiation</li> </ul>

		1				Radiation Readings			
Tank		Temperature Readings (3)	Surf	ace Level Read (OSD)	lings (1)		Leak Detection Pite (4)		
Number	Watch List	(OSD)	M.T.	FIC	ENRAF	W.F.	Rad. (6)	(OSD)	
AN-101				Nere			110		
AN-102				Next			8//		
AN-103				Nerie			N/A		
AN-104				Norm			N/A		
AN-105			O.				N/A		
AN-106				None			9//4		
AN-107						0/8	N/A		
AP-101			0/8	Close		0/8 (7)	N/A	0/8	
AP-102				None		0/8 (7)	N/A		
AP-103				None		0/6 (7)	N/A		
AP-104			0/8	Name		0/5 (7)	W/A		
AP-105				None		0/5 (7)	N/A		
AP-106				lione		0/8 (7)	N/A		
AP-107				None		0/8/67	N/A		
AP-108				200 S ( 0.00 )		0/8 (7)	N/A		
AW-101	X		0/6	Stores			N/A		
AW-102					69		N/A		
AW-103				T *****			N/A		
AW-104				None			N/A		
AW-105				None			N/A	I	
AW-106				None			NJA		
AY-101				No.		0/8	N/A	0/8	
AY-102			0/8	None			N/A		
AZ-101				None			N/A	0/8	
AZ-102					fione		N/A	0/5	
SY-101	(10)		None	None		0/6 (9)	N/A		
SY-102			0/5 (8)	None			N/A		
SY-103	×		0/6 (6)	None		O/6 (9)	N/A		
Totals: 28 tenks	5 Watch List Tanks	N/C: O	N/C: O	N/C: 0	N/C: 0	N/C: O	N/C: O	N/C: O	

# TABLE D-5. DOUBLE-SHELL TANKS MONITORING COMPLIANCE STATUS - 28 TANKS (Sheet 2 of 2)

### Footnotes:

- Some double-shell tanks have both FIC and manual tape which is used when the FIC is out of service.
   Noncompliance (N/C) will be shown when no readings are obtained. ENRAF gauges are being installed to replace FICs. The ENRAF gauges are being connected to TMACS, but some are currently being read manually.
- Psychrometric readings are taken on an "as needed" basis. No psychrometric readings are currently being taken in the double-shell tanks.
- 3. OSD specifies double-shell tank temperature limits, gradients, etc.
- 4. Applicable OSD and HNF-IP-0842, latest revisions, are used as guidelines for monitoring Leak Detection Pits. See also (6) and (7) below.
- 5. AW-102 has ENRAF, FIC and M.T. At some point the FIC will be removed.
- 6. USQ TF-97-0038, dated April 28, 1997, specifies discontinuing the use of leak detection pit radiation monitoring equipment in all double-shell tank farms where the leak detection pits are used as tertiary leak detection. This applies to all double-shell tank farms.
- Leak Detection Pit weekly readings are being obtained by Instrument Technicians in these tanks: AP-103C (for tanks AP-101 - 104) AP-105C (for tanks AP-105 - 108)
- 8. SY-102 Manual Tape has sporadic readings. ENRAF is primary device. SY-103 Manual Tape has sporadic readings. ENRAF is primary device.
- SY-101 LDP readings are above normal range. EDL #S0007 to repair it.
   SY-103 LDP readings are above normal range. EDL #241-SY-95-5 to repair it.
- 10. SY-101 was removed from the Hydrogen Watch List on January 11, 2001.

# TABLE D-6. ENRAF SURFACE LEVEL GAUGE INSTALLATION AND DATA INPUT METHODS

February 28, 2001

LEGEND

SACS

= Surveillance Analysis Computer System

TMACS

= Tank Monitor and Control System

Auto

= Automatically entered into TMACS and electronically transmitted to SACS

Manual

- Manually entered directly into SACS by surveillance personnel, from Field Data sheets

EAST A	AREA						WEST	AREA					
Tank	Installed	Input		Tank	Installed	Input	Tank	Installed	Input		Tank	Installed	Input
No.	Date	Method		No.	Date	Method	No.	Date	Method	***	No.	Date	Method
A-101	09/95	Auto		B-201	07/00	Auto	S-101	02/95	Auto		TX-101	11/95	Auto
A-102				B-202	07/00	Auto	S-102	05/95	Auto		TX-102	05/96	Auto
A-103	07/96	Auto		B-203	06/00	Auto	S-103	05/94	Auto		TX-103	12/95	Auto
A-104	05/96	Manuel		B-204	06/00	Auto	S-104	05/99	Auto		TX-104	03/96	Auto
A-105				BX-101	04/96	Auto	8-105	07/95	Auto		TX-105	04/96	Auto
A-106	01/96	Auto	-	BX-102	06/96	Auto	8-106	06/94	Auto		TX-106	04/96	Auto
AN-101	08/96	Auto	-	BX-103	04/96	Auto	S-107	06/94	Auto		TX-107	04/96	Auto
AN-102	05/00	Auto		BX-104	05/96	Auto	S-108	07/95	Auto	300	TX-108	04/96	Auto
AN-103	08/95 08/95	Auto		BX-105	03/96 07/94	Auto	S-109 S-110	08/95 08/95	Auto	880	TX-109	11/95	Auto
AN-104 AN-105	08/95	Auto Auto		BX-106 BX-107	06/96	Auto Auto	S-110 S-111	08/94	Auto	333	TX-110 TX-111	05/96 05/96	Auto
AN-106	05/00	Auto		BX-107	05/96	Auto	S-111	05/95	Auto	\$300	TX-112	05/96	Auto
AN-107	04/00	Auto		BX-109	08/95	Auto	SX-101	04/95	Auto	80% 80%	TX-113	05/96	Auto
AP-101	06/99	Auto		BX-110	06/96	Auto	SX-102	04/95	Auto	(44) (88)	TX-114	05/96	Auto
AP-102	08/99	Auto	-	BX-111	05/96	Auto	SX-103	04/95	Auto	****	TX-115	05/96	Auto
AP-103	08/99	Auto		BX-112	03/96	Auto	SX-104	05/95	Auto		TX-116	05/96	Auto
AP-104	07/99	Auto	_	BY-101			SX-105	05/95	Auto	***	TX-117	06/96	Auto
AP-105	08/99	Auto	-	BY-102	09/99	Auto	SX-108	08/94	Auto	333	TX-118	03/96	Auto
AP-106	06/99	Auto		BY-103	12/96	Auto	SX-107	09/99	Auto		TY-101	07/95	Auto
AP-107	08/99	Auto		BY-104			SX-108	09/99	Auto	333	TY-102	09/95	Auto
AP-108	08/99	Auto		BY-105			SX-109	09/98	Auto		TY-103	09/95	Auto
AW-101	08/95	Auto	882	BY-106			SX-110	09/99	Auto		TY-104	06/95	Auto
W-102	05/96	Auto		BY-107			SX-111	09/99	Auto	80	TY-105	12/95	Auto
W-103	05/96	Auto		BY-108			SX-112	09/99	Auto		TY-106	12/95	Auto
W-104	01/96	Auto	-	BY-109			SX-113	09/99	Auto	200	U-101		
W-105	06/96	Auto		BY-110	02/97	Manual	5X-114	09/89	Auto		U-102	01/96	Manual
W-106	06/96	Auto	****	BY-111	02/99	Manual	\$X-115	09/99	Manual	~~~	U-103	07/94	Auto
X-101	09/95	Auto	-	BY-112_			SY-101	07/94	Auto		U-104		
X-102	09/98	Auto	-	C-101			SY-102	06/94	Auto	20	U-105	07/94	Auto
X-103	09/95	Auto	-	C-102			SY-103	07/94	Auto		U-106	08/94	Auto
X-104	10/96	Auto	ш.	C-103	08/94	Auto	T-101	05/95	Manual	-	U-107	08/94	Auto
Y-101	03/96	Auto		C-104	04/99	Manual	T-102	06/94	Auto		U-10B	05/95	Auto
Y-102	01/98	Auto	-	C-105	06/96	Manual	T-103	07/95	Menuel	-	U-109	07/94	Auto
Z-101	06/96	Menuel	-	C-106	02/96	Auto	T-104	12/95	Manual		U-110	01/96	Manual
Z-102	11/00	Manual	-	C-107	04/95	Auto	T-105	07/95	Manual	· · · · ·	U-111	01/96	Manuel
-101 -102	07/00	Auto	-	C-108			T-106	07/95	Manual	2500	U-112		
	02/95	Auto	ж.	C-109		3	T-107	06/94	Auto	6380 2225	U-201		
-103 -104	07/00 06/00	Auto		C-110 C-111			T-108 T-109	10/95 09/94	Manual	1000	U-202	00/00	Manual
-105	08/00			C-112	03/96	Manual	T-110	05/95	Auto	-	U-203 U-204	09/98	Manual
-106	07/00	Auto		C-201		171011111111111111111111111111111111111	T-111	07/95	Manual	9200	V-2V+	V0/80	mariusi
107	06/00	Auto	-	C-202			T-112	09/95	Manual	***			
-108	07/00	Auto	***	C-203			T-201		***************************************	2000 2000			
-109	08/00	Auto	-	C-204			T-202			(A.)			
-110	07/00	Auto					T-203						
÷111	07/00	Auto		<del></del>			T-204						
-112	03/95	Auto					*		_				
	A010A		888				330			7/5			

<sup>148</sup> ENRAFs installed: 125 automatically entered into TMACS, 23 manually entered into SACS

### HNF-EP-0182, 155

# TABLE D-7. TANK MONITOR AND CONTROL SYSTEM (TMACS) February 28, 2001

Note: Indicated below are the number of tanks having at least one operating sensor monitored by TMACS.

Some tanks have more than one sensor: multiple sensors of the same type in a tank are not shown in the table (for example: 10 tanks in BY-Farm have at least one operating TC sensor and 3 tanks in BY-Farm have at least one operating RTD sensor).

Acceptance Testing Completed: Sensors Automatically Monitored by TMACS

Acce	ptance Testing Co Temper		ora Automatic	Jany Mointone	T TWINCS	<del></del>
		Resistance				
EAST AREA	Thermocouple	Thermal	ENRAF	li .		Gas
	Tree	Device	Level	Pressure	Hydrogen	Sample
Tank Farm	(TC)	(RTD)	Gauge	(b)	(c)	Flow
A-Farm (6 Tanks)	1		3		1	1
AN-Ferm (7 Tenks)	7		7	7	3	3
AP-Farm (8 Tanks)			8		I	
AW-Farm (6 Tanks)	6		6		1	1
AX-Ferm (4 Tanks)	3		4		1	
AY-Ferm (2 Tenks)			2			
AZ-Ferm (2 Tanks)						
B-Ferm (16 Tanks)	1		16			
BX-Farm (12 Tanks)	11		12			
BY-Farm (12 Tanks)	10	3	2			
C-Farm (16 Tanks)	15 (f)	11	3	1		
TOTAL EAST AREA						
(91 Tenks)	54	44	63	8	6	5
WEST AREA						<u> </u>
S-Farm (12 Tanks)	12		12	1	3	1 (e)
SX-Farm (15 Tanks)	14		14	1	7	5 (e)
SY-Farm (3 Tanks) (a)	3		3	1	2	2
T-Farm (16 Tanks)	14	1	3 (d)		1	(e)
TX-Farm (18 Tanks)	13		18			
TY-Farm (6 Tanks)	6	3	6	·		
U-Farm (16 Tanks)	15		6	4	6	6
TOTAL WEST AREA						
(86 Tanks)	77	4	62	7	19	19
TOTALS (177 Tanks)	131	8	125	15	25	24

- (a) Tank SY-101 has 2 gas sample flow sensors plus 2 vent flow sensors, and 2 ENRAFs.
- (b) Each tank has two sensors (high and low range).
- (c) Each tank has two sensors (high and low range).
- (d) T-107 Auto ENRAF O/S, manual readings taken daily
- (e) S, SX, and T-Farms five gas sample flow sensors have been unhooked or removed. Will eventually use SHMS equipment on other tanks but none scheduled yet.
- (f) C-105 acromag needs replacing. Manual readings are taken weekly.

This page intentionally left blank.

# APPENDIX E

# MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL SURVEILLANCE FACILITIES

# TABLE E-1. EAST AND WEST AREA MISCELLANEOUS UNDERGROUND STORAGE TANKS AND SPECIAL SURVEILLANCE FACILITIES

ACTIVE - still running transfers through the associated diversion boxes or pipeline encasements February 28, 2001

<b>EACILITY</b>	<b>LOCATION</b>	PURPOSE (receives waste from	:) (Gallons)	 MONITORED BY	REMARKS
EAST AREA				_	
241-A-302-A	A Farm	A-151 DB	675	SACS/ENRAF/Manually	Pumped to AW-105 7/00
241-ER-311	B Plant	ER-151, ER-152 DB	8506	SACS/ENRAF/Manually	•
241-AX-152	AX Farm	AX-152 DB	563	SACS/MT	August 2000 water added to perform integrity test
241-AZ-151	AZ Farm	AZ-702 condensate	5306	SACS/ENRAF/TMACS	Volume changes daily - pumped to AZ-101 or AZ-102 as needed
241-AZ-154	AZ Farm		25	SACS/MT	
244-BX-TK/SMP	BX Complex	DCRT - Receives from several farms	1#390	SACS/MT	Using Manual Tape for tank/sump, pumped 10/16/99 to 66.0 in. Sump O/S 2/5/01
244-A-TK/SMP	A Complex	DCRT - Receives from several farms	6830	MCS/SACS/WTF	WTF- pumped 3/99 to AP-108
A-350	A Farm	Collects drainage	270	MCS/SACS/WTF	WTF (uncorrected) pumped as needed
AR-204 A-417	AY Farm A Farm	Tanker trucks from various facilities	204 12344	 DIP TUBE SACS/WTF	Alarms on SACS-pumped to AP-108, 7/00 WTF (uncorrected) pumped 4/98
CR-003-TK/SUMP	C Farm	DCRT	2984	MT/ZIP CORD	Zip cord in sump O/S 3/11/96, water intrusion, 1/98
WEST AREA			•		
241-TX-302-C	TX Farm	TX-154 DB	155	SACS/ENRAF/Manually	
241-U-301-B	U Farm	U-151, U-152, U-153, U-252 DB	8030	SACS/ENRAF/Manually	Returned to service 12/30/93
241-UX-302-A	U Plant	UX-154 DB	3116	SACS/ENRAF/Manually	
241-S-304	S Farm	S-151 OB	130	SACS/ENRAF/Manually	Replaced S-302-A, 10/91; ENRAF installed 7/98 Sump not alarming.
244-5-TK/SMP	S Farm	From original tanks to SY-102	14195	SACS/Manually	WTF (uncorrected)
244-TX-TK/SMP	TX Farm	From original tanks to SY-102	11387	SACS/Manually	MT - pumped PFP 241-Z tank D-5 to 244-TX DCRT on 11/22/00, level now 56.50"
Vent Station Catch 1	Tank	Cross Country Transfer Line	371	 SACS/Manually	MT

Total Active Facilities

18

(a) AR-204 was pumped down to 150 gal then valve was left on and 350 gal of water went back into tank.

LEGINO: DB - Diversion Box

DCRT - Desible-Contained Receiver Tank

TK - Tank

EMP - Bump

RC - Food instrument Corporation measurement device

MT - Manual Tape

Tip Cord - surface level measurement device

WTF - Weight Time Factor - can be recorded as WTF,

CWF (corrected), and Uncorrected WTF

BACB - Surveillance Automated Control System

MCS - Monitor and Control System

Manually - Not corrected to any automated system

Ors - Out of Service

EMPAF - Surface Level Measuring Device

A Unionly denotes replacement

TABLE E-2. EAST AREA INACTIVE MISC. UNDERGROUND STORAGE TANKS AND SPECIAL SURV. FACILITIES INACTIVE - no longer receiving waste transfers

February 28, 2001

				MONITORE	<b>€D</b>
<b>EACILITY</b>	<b>LOCATION</b>	RECEIVED WASTE FROM:	(Gallons)	BY	REMARKS
216-BY-201	BY Farm	TBP Weste Line	Unknown	NM	(216-BY)
241-A-302-B	A Farm	A-152 DB	57 <b>2</b> 0	SACS/MT	Isolated 1985, Project B-138
					Interim Stabilized 1990, Rain intrusion
241-AX-151	N of PUREX	PUREX	Unknown	NM	Isolated 1985
241-B-301-B	B Ferm	B-151, B-152, B-153, B-252 DB	22250	NM	Isolated 1985 (1)
241-B-302-B	B Ferm	B-154 DB	4930	NM	Isolated 1985 (1)
241-BX-302-A	BX Farm	BR-152, BX-153, BXR-152, BYR-152 DB	840	NM	Isolated 1985 (1)
241-BX-302-B	BX Farm	BX-154 DB	1040	NM	Isolated 1985 (1)
241-BX-302-C	BX Farm	BX-155 DB	870	NM	leolated 1985 (1)
241-C-301-C	C Ferm	C-151, C-152, C-153, C-252 DB	10470	NM	Isolated 1985 (1)
241-CX-70	Hot Semi-	Transfer lines	Unknown	NM	isolated, Decommission Project.
241-CX-72	Works	Transfer lines	650	NM	See Dwg H-2-95-501, 2/5/87
241-ER-311A	SW B Plant	ER-151 DB	Unknown	NM	legisted
244-AR VAULT	A Complex	Between farms & B-Plant	Unknown	NM	Not actively being used. Systems activated for final clean-out.
244-BXR-TK/SMP-001	BX Ferm	Transfer lines	7200	NM	Interim Stabilization 1985 (1)
244-BXR-TK/SMP-002	BX Farm	Transfer lines	2180	NM	Interim Stabilization 1985 (1)
44-BXR-TK/SMP-003	BX Ferm	Transfer lines	1810	NM	Interim Stabilization 1985 (1)
244-BXR-TK/SMP-011	BX Farm	Transfer lines	7100	NM	Interim Stabilization 1985 (1)
361-B-TANK	B Plant	Drainage from B-Plant	Unknown	NM	Interim Stabilization 1985 (1)
		KODESINADEN SINESINGEN	18		M - Diversion Box CMT - Double-Contained Receiver Tank IT - Manual Tape ACM - Box williams Administral Control System

(1) SOURCE: WASTE STORAGE TANK STATUS & LEAK DETECTION CRITERIA document

TABLE E-3. WEST AREA INACTIVE MISC. UNDERGROUND STORAGE TANKS AND SPECIAL SURV. FACILITIES
INACTIVE - no longer receiving waste transfers
February 28, 2001

	IIT		

				MONITOREL	)
<u>EACILITY</u>	<b>LOCATION</b>	RECEIVED WASTE FROM:	(Gallons)	BY	REMARKS
216-TY-201	E. of TY Farm	Supernate from T-112	Unknown	NM	Isolated
231-W-151-001	N. of Z Plant	231-Z Floor drains	Unknown	NM	Inactive, last data 1974
231-W-151-002	N. of Z Plant	231-Z Floor drains	Unknown	NM	inactive, last data 1974
241-S-302	S Farm	240-S-151 DB	8376	SACS/ENRAF	Assumed Leaker EPDA 85-04
241-S-302-A	S Farm	241-S-151 DB	0	0714072111711	Assumed Leaker TF-EFS-90-042
Partially file	led with grout 2/91,	determined still assumed leaker after leak		iC readings are un	ohteinable due to dou grouted gurface
CASS mor	vitoring system retire	d 2/23/99; intrusion readings discontinue	d. S-304 replac	ed S-302-A	obtainable due to dif Broated Surface.
241-S-302-B	S Ferm	S Encasements	Unknown	NM	Isolated 1985 (1)
241-SX-302	SX Farm	SX-151 DB, 151 TB	Unknown	NM	Isolated 1987
241-SX-304	SX Farm	SX-152 Transfer Box, SX-151 DB	Unknown	NM	Isolated 1985 (1)
241-T-301	T Ferm	DB T-151, -151, -153, -252	Unknown	NM	Isolated 1985 (241-T-301B)
241-TX-302	TX Farm	TX-153 DB	Unknown	NM	Isolated 1985 (1)
241-TX-302-X-B	TX Farm	TX Encasements	Unknown	NM	Isolated 1985 (1)
241-TX-302-B	TX Farm	TX-155 DB	1600	SACS/MT	New MT installed 7/16/93
241-TX-302-B(R)	E. of TX Farm	TX-155 DB	Unknown	NM	Isolated
241-TY-302-A	TY Farm	TX-153 DB	Unknown	NM	fsolated 1985 (1)
241-TY-302-B	TY Farm	TY Encasements	Unknown	NM	Isolated 1985 (1)
241-Z-8	E. of Z Plant	Recupiex waste	Unknown	NM	Isolated, 1974, 1975
242-T-135	T Evaporator	T Evaporator	Unknown	NM	Isolated
242-TA-R1	T Evaporator	Z Plant waste	Unknown	NM	leolated
243-S-TK-1	N. of S Farm	Pers. Decon. Facility	Unknown	NM	Isolated
244-U-TK/SMP	U Farm	DCRT - Receives from several farms	Unknown	NM	Not yet in use
244-TXR VAULT	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244-TXR-TK/SMP-001	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244-TXR-TK/SMP-002	TX Farm	Transfer lines	Unknown	NM	Interim Stabilized, MT removed 1984 (1)
244 TVD TV MAD 000	TV 6	T			

Unknown

Unknown

Unknown

Unknown

NM

NM

NM

NM

Total Wast Area mactive facilities 27

LEGEND: D8 - Disersion Box, T8 - Transfer Box
DCRT - Double-Contained Receiver Tank
TK - Tank
SMP - Sump
R - Desailly denotes replacement
RC - Surface Level Monitoring Device
ACT - Manual Tape
DFS - Dut of Service
BACS - Surveillance Automated Control System
HM - Not Monitored
ENRAF - Surface Level Monitoring Device

Isolated 1970

Isolated 1985 (1)

Interim Stabilized, MT removed 1984 (1)

Interim Stabilzed, MT removed 1984 (1)

Transfer lines

Condensate from U-221

**Drainage from T-Plant** 

**Drainage from U-Plant** 

坘

244-TXR-TK/SMP-003 TX Farm

SE of U Plant

T Plant

**U Plant** 

270-W

**361-T-TANK** 

**361-U-TANK** 

# APPENDIX F LEAK VOLUME ESTIMATES

TABLE F-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 1 of 5) February 28, 2001

		Date Declared Confirmed or	Volume		Associated KiloCuries		Interim Stabilized	Leak i	Estimate
Tank Number	_	Assumed Leaker (3)	Gallons (2)		137 cs (10)		Date (11)	Updated	Reference
241-A-103	<u></u>	1987		(8)			06/88	1987	. 0
241-A-104 241-A-105	(1)	1975 1963	500 to 2500 10000 to 277000		0.8 to 1.8 85 to 760		09/78 07/79	1983 1991	(a)(q) (b)(c)
241-AX-102 241-AX-104		1988 1977	3000	(8) (6)			09/88 08/81	1989 1989	(h) (g)
241-B-101		1974		(6)			03/81	1989	(g)
241-B-103 241-B-105		1978 1978	_	(6) (6)			02/85 12/84	1989 1989	(g)
241-B-107		1980	8000	(8)			03/85	1986	(g) (d)(f)
241-B-110		1981	10000	(8)			03/85	1986	(d)
241-B-111 241-B-112		1978 1978	2000	(6)			06/85 05/85	1989 1989	(g) (g)
241-B-201		1980	1200	(8)			08/81	1984	(e)(f)
241-B-203 241-B-204		1983 1984	300 400	(8) (8)			06/84 06/84	1986 1989	(d) (g)
241-BX-101		1972		(6)	50	<i>a</i> v	09/78	1989	(g)
241-BX-102 241-BX-108		1971 1974	70000 2500		50 0.5		11/78 07/79	1986 1986	(d) (d)
241-BX-110		1976		(6) (6)			08/85	1989	(g)
241-BX-111 241-BY-103		1984 (13) 1973		(0)			03/95 11/97	1993 1983	(g) (a)
241-BY-105		1984	••	(6)			N/A	1989	(g)
241-BY-106 241-BY-107		1984 1984		(6) (8)			N/A 07/79	1989 1989	(g) (g)
241-BY-108		1972	< 5000	<del>,,</del>			02/85	1983	(a)
241-C-101		1980	20000	(8)(10	0)		11/83	1986	(d)
241-C-110 241-C-111		1984 1968	2000 5500	(8)			05/95 03/84	1989 1989	(g) (g)
241-C-201	(4)	1988	550				03/82	1987	(i)
241-C-202 241-C-203	(4)	1988 1984	450 400	(8)			08/81 03/82	1987 1986	(i) (d)
241-C-204	(4)	1988	350	(0)			09/82	1987	(i)
241-S-104		1968		(8)			12/84	1989	(g)
241-SX-104 241-SX-107		1988 1964	6000 <5000	(8)			04/00 10/7 <b>9</b>	1988 1983	(k) (a)
241-SX-108	(5)(14)	1962	2400 to		17 to 140		08/79	1991	(m)(q)(t)
241-SX-109	(5)(14)	1965	35000 <10000		(m)(q)(t) <40	(n)(t)	05/81	1992	(n)(t)
241-SX-110	,-,,,	1976		(8)		,,,,,,,	08/79	1989	(g)
241-SX-111	(14)	1974	500 to 2000		0.6 to 2.4		07/79	1986	(d)(q)(t)
241-SX-112 241-SX-113	(14)	1969 1962	30000 15000		40 8	(I)(t) (I)	07/79 11/78	198 <del>6</del> 1986	(d)(t) (d)
241-SX-114		1972		(6)			07 <i>/</i> 79	1989	(g)
241-SX-115 241-T-101		1965 1992	50000 7500	(8)	21	(0)	09/78 04/93	1992 1992	(p)
241-T-103		1974	<1000	(8)			11/83	1989	(g)
241-T-106 241-T-107		1973 1984	115000	(8) (6)	40	(1)	08/81 05/96	1986 1989	(d) (a)
241-T-108		1974	<1000	(8)			11/78	1980	(g) (f)
241-T-109 241-T-111		1974 1979, 1994 (12)	<1000 <1000				12/84 02/95	1989 1994	(g) (f)(r)
241-TX-105		1977		(6)			04/83	1989	(g)
241-TX-107	(5)	1984	2500				10/79	1986	(d)
241-TX-110 241-TX-113		1977 1974		(6) (6)			04/83 04/83	1989 1989	(g) (g)
241-TX-114		1974		(6)			04/83	1989	(g)
241-TX-115 241-TX-116		1977 1 <b>9</b> 77		(6) (6)			09/83 04/83	1989 1989	(g) (g)
241-TX-117		1977		(6)			03/83	1989	(g)
241-TY-101 241-TY-103		1973 1973	<1000 3000	(8)	0.7	m	04/83	1980 1986	(f)
241-TY-103 241-TY-104		1981	1400	(8)	0.7	117	02/83 11/83	1986	(d) (d)
241-TY-105		1960 1959	35000 20000			(1)	02/83	1986	(d)
241-TY-106 241-U-101	·	1959 1959	30000		2 20	(I) (II)	11/78 09/79	1986 1986	(d)
241-U-104		1 <b>961</b>	55000		0.09	(1)	10/78	1986	(d)
241-U-110 241-U-112		1975 1980	5000 to 8100 8500	(8) (8)	0.05	( <b>q</b> )	12/84 09/79	1986 1986	(d)(q)
67 Tenks		1960	<750,000 + 1,0	00000000000	w (2)			1950	<u>(d)</u>
32 (3 C) (1 C)				کاری د					arar (1.00 <b>0000</b> 000000000000000000000000000000

N/A = not applicable (not yet interim stabilized)

# TABLE F-1. SINGLE-SHELL LEAK VOLUME ESTIMATES (Sheet 2 of 6)

### Footnotes:

- (1) Current estimates [see reference(b)] are that 610 Kgallons of cooling water was added to Tank 241-A-105 from November 1970 to December 1978 to aid in evaporative cooling. In accordance with <u>Dangerous Waste Regulations</u> [Washington Administrative Code 173-303-070 (2)(a)(ii), as amended, Washington State Department of Ecology, 1990, Olympia, Washington], any of this cooling water that has been added and subsequently leaked from the tank must be classified as a waste and should be included in the total leak volume. In August 1991, the leak volume estimate for this tank was updated in accordance with the WAC regulations. Previous estimates excluded the cooling water leaks from the total leak volume estimates because the waste content (concentration) in the cooling water which leaked should be much less than the original liquid waste in the tank (the sludge is relatively insoluble). The total leak volume estimate in this report (10 Kgallons to 277 Kgallons) is based on the following (see References):
  - 1. Reference (b) contains an estimate of 5 Kgallons to 15 Kgallons for the initial leak prior to August 1968.
  - 2. Reference (b) contains an estimate of 5 Kgallons to 30 Kgallons for the leak while the tank was being sluiced from August 1968 to November 1970.
  - 3. Reference (b) contains an estimate of 610 Kgallons of cooling water added to the tank from
    November 1970 to December 1978 but it was estimated that the leakage was small during this period.
    This reference contains the statement "Sufficient heat was generated in the tank to evaporate most,
    and perhaps nearly all, of this water." This results in a low estimate of zero gallons leakage from
    November 1970 to December 1978.
  - 4. Reference (c) contains an estimate the 378 to 410 Kgallons evaporated out of the tank from November 1970 to December 1978. Subtracting the minimum evaporation estimate from the cooling water added estimate provides a range from 0 to 232 Kgallons of cooling water leakage from November 1970 to December 1978.

	Low Estimate	High Estimate
Prior to August 1968	5,000	15,000
August 1968 to November 1970	5,000	30,000
November 1970 to December 1978	0	232,000
Totals	10,000	277,000

- These leak volume estimates do not include (with some exceptions), such things as: (a) cooling/raw water leaks, (b) intrusions (rain infiltration) and subsequent leaks, (c) leaks inside the tank farm but not through the tank liner (surface leaks, pipeline leaks, leaks at the joint for the overflow or fill lines, etc.), and (d) leaks from catch tanks, diversion boxes, encasements, etc.
- In many cases, a leak was suspected long before it was identified or confirmed. For example, reference (d) shows that Tank 241-U-104 was suspected of leaking in 1956. The leak was "confirmed" in 1961. This report lists the "assumed leaker" date of 1961. Using present standards, Tank 241-U-104 would have been declared an assumed leaker in 1956. In 1984, the criteria designations of "suspected leaker," "questionable integrity," "confirmed leaker," "declared leaker," "borderline" and "dormant," were merged into one category now reported as "assumed leaker." See reference (f) for explanation of when, how long, and how fast some of the tanks leaked. It is highly likely that there have been undetected leaks from single-shell tanks because of the nature of their design and instrumentation.

# TABLE F-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 3 of 6)

- (4) The leak volume estimate date for these tanks is before the "declared leaker" date because the tank was in a "suspected leaker" or "questionable integrity" status; however, a leak volume had been estimated prior to the tank being reclassified.
- (5) The increasing radiation levels in drywells and laterals associated with these three tanks could be indicating continuing leak or movement of existing radionuclides in the soil. There is no conclusive way to confirm these observations.
- Methods were used to estimate the leak volumes from these 19 tanks based on the <u>assumption</u> that their cumulative leakage is approximately the same as for 18 of the 24 tanks identified in footnote (9). For more details see reference (g). The total leak volume estimate for these tanks is 150 Kgallons (rounded to the nearest Kgallons), for an average of approximately 8 Kgallons for each of 19 tanks.
- (7) The total has been rounded to the nearest 50 Kgallons. Upper bound values were used in many cases in developing these estimates. It is likely that some of these tanks have not actually leaked.
- (8) Leak volume estimate is based solely on observed liquid level decreases in these tanks. This is considered to be the most accurate method for estimating leak volumes.
- (9) The curie content shown is as listed in the reference document and is <u>not</u> decayed to a consistent date: therefore, a cumulative total is inappropriate.
- (10) Tank 241-C-101 experienced a liquid level decrease in the late 1960s and was taken out of service and pumped to a "minimum heel" in December 1969. In 1970, the tank was classified as a "questionable integrity" tank. Liquid level data show decreases in level throughout the 1970s and the tank was saltwell pumped during the 1970s, ending in April 1979. The tank was reclassified as a "confirmed leaker" in January 1980. See references (q) and (r); refer to reference (s) for information on the potential for there to have been leaks from other C-farm tanks (specifically, C-102, C-103, and C-109).
- These dates indicate when the tanks were declared to be interim stabilized. In some cases, the official interim stabilization documents were issued at a later date. Also, in some cases, the field work associated with interim stabilization was completed at an earlier date.
- (12) Tank T-111 was declared an assumed re-leaker on February 28, 1994, due to a decreasing trend in surface level measurement. This tank was pumped, and interim stabilization completed on February 22, 1995.
- (13) Tank BX-111 was declared an assumed re-leaker in April 1993. Preparations for pumping were delayed, following an administrative hold placed on all tank farm operations in August 1993. Pumping resumed and the tank was declared interim stabilized on March 15, 1995.
- (14) The leak volume and curie release estimates on SX-108, SX-109, SX-111, and SX-112 have been reevaluated using a Historical Leak Model [see reference (t)]. In general, the model estimates are much higher
  than the values listed in the table, both for volume and curies released. The values listed in the table do not
  reflect this revised estimate because, "In particular, it is worth emphasizing that this report was never meant to
  be a definitive update for the leak baseline at the Hanford Site. It was rather meant to be an attempt to view the
  issue of leak inventories with a new and different methodology." (This quote is from the first page of the
  referenced report).
- (15) In July 1998, the Washington State Department of Ecology (Ecology) directed the U. S. Department of Energy (DOE) to develop corrective action plans for eight single-shell tank farms (B/BX/BY/S/SX/T/TX/TY) where groundwater contamination likely originated from tank farm operations. A Tri-Party Agreement milestone (M-45 series) was developed that established a formalized approach for evaluating impacts on groundwater quality of losses of tank wastes to the vadose zone underlying these tank farms. Planning documents have been

# TABLE F-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 4 of 6)

completed for the S, SX, B, BX, and BY tank farms and will be completed shortly for the T, TX, and TY farms. The phase 1 field investigation is near completion in the S and SX tank farms and has begun in the B, BX, and BY farms. Field work is anticipated in FY-02 for the T, TX, and TY tank farms. The remaining four single-shell tank farms are expected to be included in corrective action plans in the near future.

All of the information included in this appendix is currently under review and significant revisions are anticipated. Recently, major tank farm vadose zone investigation efforts (such as the baseline spectral gammarsy logging of all drywells in all single-shell tank farms, as well as drilling and sampling in the SX tank farm) were completed. This appendix will be revised as a better understanding of past tank leak events is developed.

# TABLE F-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 5 of 6)

### References:

- (a) Murthy, K.S., et al, June 1983, Assessment of Single-Shell Tank Residual Liquid Issues at Hanford Site, Washington, PNL-4688, Pacific Northwest Laboratory, Richland, Washington.
- (b) WHC, 1991a, Tank 241-A-105 Leak Assessment, WHC-MR-0264, Westinghouse Hanford Company, Richland, Washington.
- (c) WHC, 1991b, Tank 241-A-105 Evaporation Estimate 1970 Through 1978, WHC-EP-0410, Westinghouse Hanford Company, Richland, Washington.
- (d) Smith, D. A., January 1986, Single-Shell Tank Isolation Safety Analysis Report, SD-WM-SAR-006, Rev. 1, Westinghouse Hanford Company, Richland, Washington.
- (e) McCann, D. C., and T. S. Vail, September 1984, Waste Status Summary, RHO-RE-SR-14, Rockwell Hanford Operations, Richland, Washington.
- (f) Catlin, R. J., March 1980, Assessment of the Surveillance Program of the High-Level Waste Storage Tanks at Hanford, Hanford Engineering Development Laboratory, Richland, Washington.
- (g) Baumhardt, R. J., May 15, 1989, Letter to R. E. Gerton, U.S. Department of Energy-Richland Operations Office, Single-Shell Tank Leak Volumes, 8901832B R1, Westinghouse Hanford Company, Richland, Washington.
- (h) WHC, 1990a, Occurrence Report, Surface Level Measurement Decrease in Single-Shell Tank 241-AX-102, WHC-UO-89-023-TF-05, Westinghouse Hanford Company, Richland, Washington.
- (i) Groth, D. R., July 1, 1987, Internal Memorandum to R. J. Baumhardt, Liquid Level Losses in Tanks 241-C-201, -202 and -204, 65950-87-517, Westinghouse Hanford Company, Richland, Washington.
- (j) Groth, D. R. and G. C. Owens, May 15, 1987, Internal Memorandum to J. H. Roecker, *Tank 103-A Integrity Evaluation*, Westinghouse Hanford Company, Richland, Washington.
- (k) Dunford, G. L., July 8, 1988, Internal Memorandum to R. K. Welty, Engineering Investigation: Interstitial Liquid Level Decrease in Tank 241-SX-104, 13331-88-416, Westinghouse Hanford Company, Richland, Washington.
- (1) ERDA, 1975, Final Environmental Statement Waste Management Operations, Hanford Reservation, Richland, Washington, ERDA-1538, 2 vols., U.S. Energy Research and Development Administration, Washington, D.C.
- (m) WHC, 1992a, Tank 241-SX-108 Leak Assessment, WHC-MR-0300, Westinghouse Hanford Company, Richland, Washington.
- (n) WHC, 1992b, Tank 241-SX-109 Leak Assessment, WHC-MR-0301, Westinghouse Hanford Company, Richland, Washington.
- (o) WHC, 1992c, Tank 241-SX-115 Leak Assessment, WHC-MR-0302, Westinghouse Hanford Company, Richland, Washington.

# TABLE F-1. SINGLE-SHELL TANK LEAK VOLUME ESTIMATES (Sheet 6 of 6)

- (p) WHC, 1992d, Occurrence Report, Apparent Decrease in Liquid Level in Single Shell Underground Storage Tank 241-T-101, Leak Suspected; Investigation Continuing, RL-WHC-TANKFARM-1992-0073, Westinghouse Hanford Company, Richland, Washington.
- (q) WHC,1990b, A History of the 200 Area Tank Farms, WHC-MR-0132, Westinghouse Hanford Company, Richland, Washington.
- (t) WHC, 1993a, Assessment of Unsaturated Zone Radionuclide Contamination Around Single-Shell Tanks 241-C-105 and 241-C-106, WHC-SD-EN-TI-185, REV OA, Westinghouse Hanford Company, Richland, Washington.
- (s) WHC, 1994, Occurrence Report, Apparent Liquid Level Decrease in Single Shell Underground Storage Tank 241-T-111; Declared an Assumed Re-Leaker, RL-WHC-TANKFARM-1994-0009, Westinghouse Hanford Company, Richland, Washington.
- (t) HNF, 1998, Agnew, S. F. and R. A. Corbin, August 1998, Analysis of SX Farm Leak Histories Historical Leak Model, (HLM), HNF-3233, Rev. 0, Los Alamos National Laboratory, Los Alamos, New Mexico

This page intentionally left blank

### APPENDIX G

SINGLE-SHELL TANKS INTERIM STABILIZATION, AND CONTROLLED, CLEAN AND STABLE (CCS) STATUS

TABLE G-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (Sheet 1 of 3) February 28, 2001

_		Interim	<b> </b>				Interim	]		<b>.</b> .		Interim	
Tank	Tank	Stebil.	Stabil.		Tenk	Tank	Stabil.	Stebil.		Tenk	Tank	Stabil.	Stabil
Number	Integrity	<u>Date (1)</u>	Method		<u>Number</u>	Integrity	Date (1)	Method		<u>Number</u>	Integrity	Date (1)	Mathe
\-101	SOUND	N/A			C-101	ASMD LKR	11/83	AR		T-108	ASMD LKR	11/78	AR
-102	SOUND	08/89	SN	<b>\$</b>	C-102	SOUND	09/95	JET		T-109	ASMD LKR	12/84	AR
\-103	ASMD LKR	06/88	AR		C-103	SOUND	N/A			T-110	SOUND	01/00 (5)	JET
\-104	ASMD LKR	09/78	AR		C-104	SOUND	09/89	\$N		T-111	ASMD LKR	02/95	JET
-105	ASMD LKR	07/79	AR	, 300 , 300	C-105	SOUND	10/95	AR		T-112	SOUND	03/81	AR(2)(
\-106	SOUND	08/82	AR		C-106	SOUND	N/A		60 N 6000	T-201	SOUND	04/81	AR (3
X-101	SOUND	N/A			C-107	SOUND	09/85	JET		T-202	SOUND	08/81	AR
X-102	ASMD LKR	09/88	SN		C-108	SOUND	03/84	AR		T-203	SOUND	04/81	AR
X-103	SOUND	08/87	AR		C-109	SOUND	11/83	AR		T-204	SOUND	08/81	AR
X-104	ASMD LKR	08/81	AR	***	C-110	ASMD LKR	05/95	JET		TX-101	SOUND	02/84	AR
-101	ASMD IKR	03/81	SN		C-111	ASMD LKR	03/84	SN	*	TX-102	SOUND	04/83	JET
-102	SOUND	08/86	SN		C-112	SOUND	09/90	AR	2004 2004	TX-103	SOUND	08/83	JET
-103	ASMD IKR	02/86	SN	2000 2000	C-201	ASMD LKR	03/82	AR	200	TX-104	SOUND	09/79	SN
-104	SOUND	06/66	SN		C-202	ASMD LKR	08/81	AR		TX-105	ASMD LKR	04/83	JET
-105	ASMD IKR	12/84	AR	<b>%</b> 3	C-203	ASMD LKR	03/82	AR		TX-106	SOUND	06/83	JET
-106	SOUND	03/85	SN		C-204	ASMD LKR	09/82	AR	ं	TX-107	ASMD LKR	10/79	AR
-107	ASMD LKR	03/85	SN		S-101	SOUND	N/A			TX-108	SOUND	03/83	JET
-108	SOUND	06/86	SN		8-102	SOUND	N/A			TX-109	SOUND	04/83	JET
-109	SOUND	04/85	SN		S-103	SOUND	04/00	JET (6)		TX-110	ASMD LKR	04/83	JET
-110	ASMD LKR	12/84	AR	۰	S-104	ASMD LKR	12/84	AR		TX-111	SOUND	04/83	JET
-111	ASMD LKR	06/85	SN	00000 20000	S-105	SOUND	09/88	JET		TX-112	SOUND	04/83	JET
-112	ASMID LKR	06/85	SN	8	S-106	SOUND	02/01	JET (10)		TX-113	ASMD LKR	04/83	JET
-201	ASMD LKR	08/81	AR (3)		S-107	SOUND	N/A			TX-114	ASMD LKR	04/83	JET
-202	SOUND	06/85	AR(2)	\$	S-108	SOUND	12/96	JET		TX-115	ASMD LKR	09/83	JET
-203	ASMD LKR	06/84	AR		S-109	SOUND	N/A			TX-116	ASMD LKR	04/83	JET
-204	ASMD LKR	06/84	AR		S-110	SOUND	01/97	JET		TX-117	ASMD LKR	03/83	JET
IX-101	ASMD LKR	09/78	AR	<b>1</b>	S-111	SOUND	N/A			TX-118	SOUND	04/83	JET
X-102	ASMD LKR	11/78	AR		S-112	SOUND	N/A			TY-101	ASMD LKR	04/83	JET
X-103	SOUND	11/83	AR(2)	क्षुण्या १८५८ च	8X-101	SOUND	N/A		266 620	TY-102	SOUND	09/79	AR
X-104	SOUND	09/89	SN	986	SX-102	SOUND	N/A		Š	TY-103	ASMD LKR	02/83	JET
X-105	SOUND	03/81	SN	<b></b>	SX-103	SOUND	N/A			TY-104	ASMD LKR	11/83	AR
3X-106	SOUND	07/96	SN		SX-104	ASMD LKR	04/00	JET (7)		TY-105	ASMD LKR	02/83	JET
X-107	SOUND	09/90	JET	ħ.	SX-105	SOUND	N/A			TY-106	ASMD LKR	11/78	AR
X-108	ASMD LKR	07/79	SN		SX-106	SOUND	05/00	JET (8)		U-101	ASMD LKR	09/79	AR
X-109	SOUND	09/90	JET		SX-107	ASMD LKR	10/79	AR		U-102	SOUND	N/A	
X-110	ASMD LKR	08/85	SN		SX-108	ASMO LKR	08/79	AR		U-103	SOUND	09/00	JET (9
X-111	ASMD LKR	03/95	JET		8X-109	ASMD LKR	05/81	AR		U-104	ASMD LKR	10/78	AR
X-112	SOUND	09/90	JET		SX-110	ASMD LKR	08/79	AR		U-105	SOUND	N/A	
Y-101	SOUND	05/84	JET		SX-111	ASMO LKR	07/79	SN	90	U-106	SOUND	N/A	
Y-102	SOUND	04/95	JET		SX-112	ASMD LKR	07/79	AR		U-107	SOUND	N/A	
Y-103	ASMD LKR	11/97	JET		SX-113	ASMD LKR	11/78	AR		U-108	SOUND	N/A	
Y-104	SOUND	01/85	JET		SX-114	ASMD LKR	07/79	AR	66946 6666	U-109	SOUND	N/A	
Y-105	ASMD LKR	N/A			SX-115	ASMD LKR	09/78	AR		U-110	ASMD LKR	12/84	AR
Y-106	ASMD LKR	N/A			T-101	ASMD LKR	04/93	SN	20/10 2000	Ü-111	SOUND	N/A	
Y-107	ASMD LKR	07/79	JET		T-102	SOUND	03/81	AR(2)(3)	۵.,	U-112	ASMD LKR	09/79	AR
Y-108	ASMD LKR	02/85	JET		T-103	ASMD LKR	11/83	AR		U-201	SOUND	08/79	AR
Y-109	SOUND	07/97	JET		T-104	SOUND	11/99 (4)	JET	9	U-202	SOUND	08/79	SN
Y-110	SOUND	01/85	JET		T-105	SOUND	06/87	AR	8	U-203	SOUND	08/79	AR
Y-111	SOUND	01/85	JËT		T-106	ASMD LKR	08/81	AR	**	U-204	SOUND	08/79	SN
Y-112	SOUND	06/84	JET		T-107	ASMD LKR	06/96	JET					
EGEND:  AR = Administratively interim stabilized  JET = Saltwell jet pumped to remove drainable interstitial liquid				Interim Stabilized Tanks Not Yet Interim Stabilized				12					
SN = Supernate pumped (Non-Jet pumped) N/A = Not yet,interim stabilized ASMD LKR = Assumed Leaker						Total	Single-Shell *	Tanks	14				

# TABLE G-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (sheet 2 of 3)

#### Footnotes:

- (1) These dates indicate when the tanks were actually interim stabilized. In some cases, the official interim stabilization documents were issued at a later date.
- (2) Although tanks, BX-103, T-102 and T-112 met the interim stabilization administrative procedure at the time they were stabilized, they no longer meet the recently updated administrative procedure. The tanks were reevaluated in 1996 and memo 9654456, J. H. Wicks to Dr. J. K. McClusky, DOE-RL, dated September 1996, was issued which recommended that no further pumping be performed on these tanks, based on an economic evaluation.

Document RPP-5556, Rev. 0, "Updated Drainable Interstitial Liquid Volume Estimates for 119 Single-Shell Tanks Declared Stabilized," J. G. Field, February 7, 2000, states that five tanks no longer meet the stabilization criteria (BX-103, T-102, and T-112 exceed the supernate criteria, and BY-103 and C-102 exceed the DIL criteria).

An intrusion investigation was completed on tank B-202 in 1996 because of a detected increase in surface level. As a result of this investigation, it was determined that this tank no longer meets the recently updated administrative procedure for 200 series tanks.

- Original Interim Stabilization data are missing on four tanks: B-201, T-102, T-112, and T-201. Document HNF-SD-RE-TI-178, Rev. 7, dated February 9, 2001, added three additional tanks to those missing stabilization data: A-104, BX-101, and SX-115.
- (4) Tank 241-T-104 was Interim Stabilized on November 19, 1999. In-tank video taken October 7, 1999, shows the surface is clearly sludge-type waste with no saltcake present. No visible water on surface. Waste surface appears level across tank with numerous cracks. There is a minimal collapsed area around the saltwell screen, with no visible bottom.
- (5) Tank 241-T-110 was Interim Stabilized on January 5, 2000, due to major equipment failure. An in-tank video taken October 7, 1999 (pumping was discontinued on August 12, 1999), showed the surface of this tank as smooth, brown-tinted sludge with visible cracks.
- (6) Tank 241-S-103 was declared Interim Stabilized April 18, 2000. The surface is a rough, black and brown-colored waste with yellow patches of saltcake visible throughout. The surface appears to be damp but not saturated, and shows irregular cracking typically seen with surfaces beginning to dry out. A pool of supernatant liquid (10 feet in diameter, 5 feet deep, 1.0 Kgallons) is visible from video observations.
- (7) Tank 241-SX-104 was declared Interim Stabilized April 26, 2000, due to major equipment failure. The surface is a rough, yellowish gray saltcake waste with an irregular surface of visible cracks and shelves that were created as the surface dried out. The waste surface appears to be dry and shows no standing water within the tank.
- (8) Tank 241-SX-106 was declared Interim Stabilized May 5, 2000. The surface is a smooth, white-colored saltcake waste. The surface level slopes slightly from the tank sidewall down to a large depression in the center of the tank. A second depression surrounds both saltwell screens and an abandoned LOW. The waste surfaces appear dry and show no standing water within the tank.

# TABLE G-1. SINGLE-SHELL TANKS INTERIM STABILIZATION STATUS (sheet 3 of 3)

- (9) Tank 241-U-103 was declared Interim Stabilized September 11, 2000. The surface is a brown colored waste with irregular patches of white salt crystal. Approximately 30% of the waste surface is covered by the salt formations. The surface level slopes slightly from the tank sidewall down to the first of two depressions in the center of the tank. The waste surface appears dry and shows signs of drying and cracking due to saltwell pumping. LOW readings indicate an average adjusted ILL of 60.2 inches. There is a small pool of supernatant liquid estimated to be 500 gallons.
- (10) Tank 241-S-106 was declared Interim Stabilized on February 1, 2001. The surface is a rough, brown and yellow-colored saltcake waste with an irregular surface of mounds and saltcake crystals that were created as the surface was dried out. The waste surface appears to be dry and shows no standing water within the tank. There is no evidence of supernatant liquid from video observations. The waste surface slopes gradually from the tank sidewall to the depression in the center of the tank. The depression surrounds both of the saltwell screens, but does not extend around the temperature probe and ENRAF devices.

# TABLE G-2. SINGLE-SHELL TANK INTERIM STABILIZATION MILESTONES February 28, 2001 (sheet 1 of 2)

New single-shell tank interim stabilization milestones were negotiated in 1999 and are identified in the "Consent Decree." The Consent Decree was approved on August 16, 1999.

# CONSENT DECREE Attachments A-1 and A-2

Following is the schedule for pumping liquid waste from the remaining twenty-nine (29) single-shell tanks. This schedule is enforceable pursuant to the terms of the Decree except for the "Project Pumping Completion Dates," which are estimates only and not enforceable. (Note: Schedule does not include C-106)

Tank		Projected Pumping	Actual Pumping	Projected Pumping	Interim Stabilization	
Designation		Start Date	Start Date	Completion Date	Date	
1.	T-104	Already initiated	March 24, 1996	May 30, 1999	November 19, 1999	
2.	T-110	Already initiated	May 12, 1997	May 30, 1999	January 5, 2000	
3.	SX-104	Already initiated	September 26, 1997	December 30, 2000	April 26, 2000	
4	SX-106	Already initiated	October 6, 1998	December 30, 2000	May 5, 2000	
5.	S-102	July 31, 1999	March 18, 1999	March 30, 2001		
6.	S-106	July 31, 1999	April 16, 1999	March 30, 2001	February 1, 2001	
<b>7</b>	S-103	July 31, 1999	June 4, 1999	March 30, 2001	April 18, 2000	
8.	U-103*	June 15, 2000	September 26, 1999	April 15, 2002	September 11, 2000	
9.	U-105*	June 15, 2000	December 10, 1999	April 15, 2002	_	
10.	U-102*	June 15, 2000	January 20, 2000	April 15, 2002		
11.	U-109*	June 15, 2000	March 11, 2000	April 15, 2002		
12.	A-101	October 30, 2000	May 6, 2000	September 30, 2003		
13.	AX-101	October 30, 2000	July 29, 2000	September 30, 2003		
14.	SX-105	March 15, 2001	August 8, 2000	February 28, 2003	•	
15.	SX-103	March 15, 2001	October 26, 2000	February 28, 2003		
16.	SX-101	March 15, 2001	November 22, 2000	February 28, 2003		
17.	U-106*	March 15, 2001	August 24, 2000	February 28, 2003		
18.	BY-106	July 15, 2001		June 30, 2003		
19.	BY-105	July 15, 2001		June 30, 2003		
20.	U-108	December 30, 2001		August 30, 2003		
21.	U-107	December 30, 2001		August 30, 2003		
22.	S-111	December 30, 2001		August 30, 2003	•	
<b>23</b> .	SX-102	December 30, 2001		August 30, 2003		
24.	U-111	November 30, 2002		September 30, 2003		
<b>25</b> .	S-109	November 30, 2002	September 23, 2000	September 30, 2003		
<b>26</b> .	S-112	November 30, 2002	-	September 30, 2003		
27.	S-101	November 30, 2002		September 30, 2003		
28.	S-107	November 30, 2002		September 30, 2003		

No later than December 30, 2000, DOE will determine whether the organic layer and pumpable liquids will be pumped from this tank together or separately, and will establish a deadline for initiating pumping of this tank. The parties will incorporate the initiation deadline into this schedule as provided in Section VI of the Decree.

ORP issued a letter to WDOE on December 22, 2000, meeting the requirements of this milestone.

<sup>\*</sup> Tanks containing organic complexants.

# TABLE G-2. SINGLE-SHELL TANK INTERIM STABILIZATION MILESTONES (sheet 2 of 2)

Completion of Interim Stabilization. DOE will complete interim stabilization of all 29 single-shell tanks listed above by September 30, 2004.

#### Percentage of Pumpable Liquid Remaining to be Removed:

93% of Total Liquid	9/30/1999 (1)
38% of Organic Complexed Pumpable Liquids	9/30/2000 (2)
5% of Organic Complexed Pumpable Liquids	9/30/2001
18% of Total Liquid	9/30/2002
2% of Total Liquid	9/30/2003

The "percentage of pumpable liquid remaining to be removed" is calculated by dividing the volume of pumpable liquid remaining to be removed from tanks not yet interim stabilized by the sum of the total amount of liquid that has been pumped and the pumpable liquid that remains to be pumped from all tanks.

- (1) The Pumpable Liquid Remaining was reduced to 88%, by 9/30/99, exceeding this milestone. Reference LMHC-9957926 R1, D. I. Allen, LHMC RPP to D. C. Bryson, DOE-OPP, dated October 26, 1999
- (2) The Complexed Pumpable Liquid Remaining was reduced to 38%, by 9/15/00. Reference CHG-0004752, R. F. Wood, CHG, to J. J. Short, DOE-RPP, dated September 13, 2000.

TABLE G-3. SINGLE-SHELL TANKS STABILIZATION STATUS SUMMARY February 28, 2001

Partial Interim Isolated (PI)	Intrusion Preventi	on Completed (IP)	Interim Stabiliz	zed (IS)
EAST AREA	EAST AREA	WEST AREA	EAST AREA	WEST AREA
A-101	A-103	S-104	A-102	S-103
A-102	A-104	\$-1 <b>0</b> 5	A-103	S-104
·	A-105		A-104	S-105
AX-101	A-106	SX-107	A-105	S-106
		\$X-106	A-106	S-108
BY-102	AX-102	\$X-109		S-110
BY-103	AX-103	8X-110	AX-102	
BY-105	AX-104	SX-111	AX-103	SX-104
BY-106		\$X-112	AX-104	SX-106
BY-109	B-FARM - 16 tanks	SX-113		SX-107
	BX-FARM - 12 tanks	SX-114	B-FARM - 16 tanks	SX-108
C-103		8X-115	BX-FARM - 12 tanks	SX-109
C-105	BY-101			SX-110
C-106	BY-104	T-102	BY-101	SX-111
East Area 11	BY-107	T-103	BY-102	SX-112
	§8Y-108	T-105	BY-103	SX-113
<u>WEST AREA</u>	BY-110	T-106	BY-104	SX-114
S-101	BY-111	T-108	BY-107	SX-115
S-102	BY-112	T-109	BY-108	
S-103		T-112	BY-109	T-Farm - 16 tanks
S-106	C-101	T-201	BY-110	TX-FARM - 18 tanks
S-107	C-102	T-202	BY-111	TY-FARM - 6 tanks
S-108	C-104	T-203	BY-112	
S-10 <del>9</del>	C-107	T-204		U-101
\$-110	C-108		C-101	U-103
S-111	C-109	TX-FARM - 18 tanks	C-102	U-104
S-112	C-110	TY-FARM - 6 tanks	C-104	U-110
·	C-111		C-105	U-112
SX-101	C-112	U-101	C-107	U-201
SX-102	C-201	U-104	C-108	U-202
SX-103	C-202	U-112	C-109	U-203
SX-104	C-203	U-102	C-110	U-204
SX-105	C-204	U-202	C-111	
SX-106 ,	East Area 56	U-203	C-112	West Area of Total 126
		ับ-204	C-201	
T-101	·	West Area 53	C-202	
T-104		(dia 108	C-203	
T-107			C-204	
T-110			Essi Area 80	
T-111				,
U-102	Controlled, Clean, and	i Stable (CCS)		
U-103		<del></del>		
U-105	EAST AREA	WEST AREA		
U-106	BX-FARM - 12 Tanks	TX-FARM - 18 tanks		
U-107		TY FARM - 6 tanks		
U-108	East Aires 12	Walking 24	Ĭ	
U-109		West Arm 24 Tring 35		
U-110				
U-111	Note: CCS activities ha	ve been deferred		
	until funding is availabl	e.		
West Area 29 Total 40		<del></del>		
*	Ŗ	•	8	

This page intentionally left blank.

## APPENDIX H

# TANKS AND EQUIPMENT CODE AND STATUS DEFINITIONS

# TABLE H - 1. TANK AND EQUIPMENT CODE/STATUS DEFINITIONS February 28, 2001

#### 1. TANK STATUS CODES

#### WASTE TYPE (also see definitions, section 2 below)

AW	Aging Waste (Neutralized Current Acid Waste [NCAW])
CC	Complexant Concentrate Waste
CP	Concentrated Phosphate Waste
DC	Dilute Complexed Waste
DN	Dilute Non-Complexed Waste
DSS	Double-Shell Slurry
DSSF	Double-Shell Slurry Feed
NCPLX	Non-Complexed Waste
PD	Plutonium-Uranium Extraction (PUREX) Neutralized Cladding
	Removal Waste (NCRW), transuranic waste (TRU)

#### TANK USE (DOUBLE-SHELL TANKS ONLY)

CWHT	Concentrated Waste Holding Tank
DRCVR	Dilute Receiver Tank
EVFD	Evaporate Feed Tank
SRCVR	Slurry Receiver Tank

#### 2. **DEFINITIONS**

#### **WASTE TANKS - GENERAL**

#### Waste Tank Safety Issue

A potentially unsafe condition in the handling of waste material in underground storage tanks that requires corrective action to reduce or eliminate the unsafe condition.

#### Watch List Tank

An underground storage tank containing waste that requires special safety precautions because it may have a serious potential for release of high level radioactive waste because of uncontrolled increases in temperature or pressure. Special restrictions have been placed on these tanks by "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991, November 5, 1990, Public Law 101-510, (also known as the Wyden Amendment).

#### Characterization

Characterization is understanding the Hanford tank waste chemical, physical, and radiological properties to the extent necessary to insure safe storage and interim operation, and ultimate disposition of the waste.

#### **WASTE TYPES**

#### Aging Waste (AW)

High level, first cycle solvent extraction waste from the PUREX plant (NCAW)

#### Concentrated Complexant (CC)

Concentrated product from the evaporation of dilute complexed waste.

#### Concentrated Phosphate Waste (CP)

Waste originating from the decontamination of the N Reactor in the 100 N Area. Concentration of this waste produces concentrated phosphate waste.

#### Dilute Complexed Waste (DC)

Characterized by a high content of organic carbon including organic complexants: ethylenediaminetetraacetic acid (EDTA), citric acid, and hydroxyethyl-ethylenediaminetriacetic acid (HEDTA), being the major complexants used. Main sources of DC waste in the DST system are saltwell liquid inventory (from SSTs).

#### Dilute Non-Complexed Waste (DN)

Low activity liquid waste originating from T and S Plants, the 300 and 400 Areas, PUREX facility (decladding supernatant and miscellaneous wastes), 100 N Area (sulfate waste), B Plant, saltwells, and PFP (supernate).

#### Double-Shell Slurry (DSS)

Waste that exceeds the sodium aluminate saturation boundary in the evaporator without exceeding receiver tank composition limits. For reporting purposes, DSS is considered a solid.

#### Double-Shell Slurry Feed (DSSF)

Waste concentrated just before reaching the sodium aluminate saturation boundary in the evaporator without exceeding receiver tank composition limits. This form is not as concentrated as DSS.

#### Non-complexed (NCPLX)

General waste term applied to all Hanford Site (NCPLX) liquors not identified as complexed.

#### PUREX Decladding (PD)

PUREX Neutralized Cladding Removal Waste (NCRW) is the solids portion of the PUREX plant neutralized cladding removal waste stream; received in Tank Farms as a slurry. NCRW solids are classified as transuranic (TRU) waste.

#### Drainable Interstitial Liquid (DIL)

Interstitial liquid that is not held in place by capillary forces, and will therefore migrate or move by gravity. (See also Section 4 below)

#### Supernate

The liquid above the solids or in large liquid pools covered by floating solids in waste storage tanks. (See also Section 4 below)

#### Ferrocvanide

A compound of iron and cyanide commonly expressed as FeCN. The actual formula for the ferrocyanide anion is  $[Fe(CN)_6]^{-4}$ .

#### INTERIM STABILIZATION (Single-Shell Tanks only)

#### Interim Stabilized (IS)

A tank which contains less than 50 Kgallons of drainable interstitial liquid and less than 5 Kgallons of supernatant liquid. If the tank was jet pumped to achieve interim stabilization, then the jet pump flow or saltwell screen inflow must also have been at or below 0.05 gpm before interim stabilization criteria is met.

#### Jet Pump

The jet pump system includes 1) a jet assembly with foot valve mounted to the base of two pipes that extend from the top of the well to near the bottom of the well casing inside the saltwell screen, 2) a centrifugal pump to supply power fluid to the down-hole jet assembly, 3) flexible or rigid transfer jumpers, 4) a flush line, and 5) a flowmeter. The jumpers contain piping, valves, and pressure and limit switches.

The centrifugal pump and jet assembly are needed to pump the interstitial liquid from the saltwell screen into the pump pit, nominally a 40-foot elevation rise. The power fluid passes through a nozzle in the jet assembly and acts to convert fluid pressure head to velocity head, thereby reducing the pressure in the jet assembly chamber. The reduction in pressure allows the interstitial liquid to enter the jet assembly chamber and mix with the power fluid. Velocity head is converted to pressure head above the nozzle, lifting power fluid, and interstitial liquid to the pump pit. Pumping rates vary from 0.05 gallons to about 4 gpm.

#### Saltwell Screen

The saltwell system is a 10-inch diameter saltwell casing consisting of a stainless steel saltwell screen welded to a Schedule 40 carbon steel pipe. The casing and screen are to be inserted into the 12-inch tank riser located in the pump pit. The stainless steel screen portion of the system will extend through the tank waste to near the bottom of the tank. The saltwell screen portion of the casing is an approximately 10-foot length of 300 Series, 10-inch diameter, stainless steel pipe with screen openings (slots) of 0.05 inches.

#### **Emergency Pumping Trailer**

A 45-foot tractor-type trailer is equipped to provide storage space and service facilities for emergency pumping equipment: this consists of two dedicated jet pump jumpers and two jet pumps, piping and dip tubes for each, two submersible pumps and attached piping, and a skid-mounted Weight Factor Instrument Enclosure (WFIE) with an air compressor and electronic recording instruments. The skid also contains a power control station for the pumps, pump pit leak detection, and instrumentation. A rack for over 100 feet of overground double-contained piping is also in the trailer.

#### INTRUSION PREVENTION (ISOLATION) Single-Shell Tanks only

#### Partially Interim Isolated (PI)

The administrative designation reflecting the completion of the physical effort required for Interim Isolation except for isolation of risers and piping that is required for jet pumping or for other methods of stabilization.

#### Interim Isolated (II)

The administrative designation reflecting the completion of the physical effort required to minimize the addition of liquids into an inactive storage tank, process vault, sump, catch tank, or diversion box. In June 1993, Interim Isolation was replaced by Intrusion Prevention.

#### Intrusion Prevention (IP)

Intrusion Prevention is the administrative designation reflecting the completion of the physical effort required to minimize the addition of liquids into an inactive storage tank, process vault, sump, catch tank, or diversion box. Under no circumstances are electrical or instrumentation devices disconnected or disabled during the intrusion prevention process (with the exception of the electrical pump).

#### Controlled, Clean, and Stable (CCS)

Controlled, Clean, and Stable reflects the completion of several objectives: "Controlled" - provide remote monitoring for required instrumentation and implement controls required in the TWRS Authorization Basis; "Clean" - remove surface soil contamination and downpost the Tank Farms to RBA/URMA/RA radiological control status, remove abandoned equipment, and place reusuable equipment in compliant storage; and "Stable" - remove pumpable liquids from the SSTs and IMUSTs and isolate the tanks.

#### TANK INTEGRITY

#### Sound

The integrity classification of a waste storage tank for which surveillance data indicate no loss of liquid attributed to a breach of integrity.

#### Assumed Leaker

The integrity classification of a waste storage tank for which surveillance data indicate a loss of liquid attributed to a breach of integrity.

#### Assumed Re-Leaker

A condition that exists after a tank has been declared as an "assumed leaker" and then the surveillance data indicates a new loss of liquid attributed to a breach of integrity.

#### TANK INVESTIGATION

#### Intrusion

A term used to describe the infiltration of liquid into a waste tank.

#### SURVEILLANCE INSTRUMENTATION

#### Drywells

Historically, the drywells were monitored with gross logging tools as part of a secondary leak monitoring system. In some cases, neutron-moisture sensors were used to monitor moisture in the soil as a function of well depth, which could be indicative of tank leakage. The routine gross gamma logging data were stored electronically from 1974 through 1994. The routine gross gamma logging program ended in 1994. A program was initiated in 1995 to log each of the available drywells in each tank farm with a spectral gamma logging system. The spectral gamma logging system provides quantitative values for gamma-emitting radionuclides. The baseline spectral gamma logging database is available electronically.

Repeat spectral drywell scans are not part of the established Tank Farm leak detection program, but can be run on request if special needs arise. A select subset of drywells is routinely monitored by the Vadose Zone Characterization Project to assess movement of gamma-emitting radionuclides in the subsurface.

#### **Laterals**

Laterals are horizontal drywells positioned under single-shell waste storage tanks to detect radionuclides in the soil which could be indicative of tank leakage. These drywells can be monitored by radiation detection probes. Laterals are 4-inch inside diameter steel pipes located 8 to 10 feet below the tank's concrete base. There are three laterals per tank. Laterals are located only in A and SX farms. There are currently no functioning laterals and no plan to prepare them for use.

#### Surface Levels

The surface level measurements in all waste storage tanks are monitored by manual or automatic conductivity probes, and recorded and transmitted or entered into the Surveillance Analysis Computer System (SACS).

#### **Automatic FIC**

An automatic waste surface level measurement device is manufactured by the Food Instrument Company (FIC). The instrument consists of a conductivity electrode (plummet) connected to a calibrated steel tape, a steel tape reel housing and a controller that automatically raises and lowers the plummet to obtain a waste surface level reading. The controller can provide a digital display of the data and until February 1999, the majority of the FICs transmitted readings to the CASS. Since CASS retirement, all FIC gauges are read manually. FICs are being replaced by ENRAF detectors (see below).

#### ENRAF 854 ATG Level Detector

FICs and some manual tapes are in the process of being replaced by the ENRAF ATG 854 level detector. The ENRAF gauge, fabricated by ENRAF Incorporated, determines waste level by detecting variations in the weight of a displacer suspended in the tank waste. The displacer is connected to a wire wound onto a precision measuring drum. A level causes a change in the weight of the displacer which will be detected by the force transducer. Electronics within the gauge causes the servo motor to adjust the position of the displacer and compute the tank level based on the new position of the displacer drum. The gauge displays the level in decimal inches. The first few ENRAFs that received remote reading capability transmit liquid level data via analog output to the Tank Monitor and Control System (TMACS). The remaining ENRAFs and future installations will transmit digital level data to TMACS via an ENRAF Computer Interface Unit (CIU). The CIU allows fully remote communication with the gauge, minimizing tank farm entry.

#### Annulus

The annulus is the space between the inner and outer shells on DSTs only. Drain channels in the insulating and/or supporting concrete carry any leakage to the annulus space where conductivity probes are installed. The annulus conductivity probes and radiation detectors are the primary means of leak detection for all DSTs.

#### Liquid Observation Well (LOW)

In-tank liquid observation wells are used for monitoring the interstitial liquid level (ILL) in single-shell waste storage tanks. The wells are usually constructed of fiberglass or TEFZEL-reinforced epoxy-polyester resin (TEFZEL, a trademark of E. I. du Pont de Nemours & Company). There are a few LOWs constructed of steel. LOWs are sized to extend to within 1 inch of the bottom of the waste tank, are sealed at their bottom ends and have a nominal outside diameter of 3.5 inches. Two probes are used to monitor changes in the ILL; gamma and neutron, which can indicate intrusions or leakage by increases or decreases in the ILL. There are 65 LOWs (64 are in operation) installed in SSTs that contain or are capable of containing greater than 50 Kgallons of drainable interstitial liquid, and in two DSTs only. The LOWs installed in two DSTs, (SY-102 and AW-103 tanks), are used for special, rather than routine, surveillance purposes only.

#### Thermocouple (TC)

A thermocouple is a thermoelectric device used to measure temperature. More than one thermocouple on a device (probe) is called a thermocouple tree. In DSTs there may be one or more thermocouple trees in risers in the primary tank. In addition, in DSTs only, there are thermocouple elements installed in the insulating concrete, the lower primary tank knuckle, the secondary tank concrete foundation, and in the outer structural concrete.

These monitor temperature gradients within the concrete walls, bottom of the tank, and the domes. In SSTs, one or more thermocouples may be installed directly in a tank, although some SSTs do not have any trees installed. A single thermocouple (probe) may be installed in a riser, or lowered down an existing riser or LOW. There are also four thermocouple laterals beneath Tank 105-A in which temperature readings are taken in 34 thermocouples.

#### In-tank Photographs and Videos

In-tank photographs and videos may be taken to aid in resolving in-tank measurement anomalies and determine tank integrity. Photographs and videos help determine sludge and liquid levels by visual examination.

#### TERMS/ACRONYMS

CCS Controlled, Clean and Stable (tank farms)

FSAR Final Safety Analysis Report (replaces BIOS, effective October 18, 1999)

II Interim Isolated

IP Intrusion Prevention Completed

IS Interim Stabilized

MT/FIC/ENRAF Manual Tape, Food Instrument Corporation, ENRAF Corporation (surface level measurement devices)

OSD Operating Specifications Document

PI Partial Interim Isolated

SAR Safety Analysis Reports

SHMS Standard Hydrogen Monitoring System

TMACS Tank Monitor and Control System

TPA Hanford Federal Facility Consent and Compliance Order, "Washington State Department of

Ecology, U. S. Environmental Protection Agency, and U. S. Department of Energy," Fourth

Amendment, 1994 (Tri-Party Agreement)

TSR Technical Safety Requirements

USO Unreviewed Safety Question

Wyden Amendment "Safety Measures for Waste Tanks at Hanford Nuclear Reservation," Section 3137 of the National Defense Authorization Act for Fiscal Year 1991, November 5, 1990, Public Law 101-510.

# 3. <u>INVENTORY AND STATUS BY TANK - COLUMN VOLUME CALCULATIONS AND</u> DEFINITIONS FOR TABLE A-6 (SINGLE-SHELL TANKS)

COLUMN HEADING	COLUMN VOLUME CALCULATIONS (Underlined)/DEFINITIONS			
Total Waste	Solids volume plus Supernatant liquid. Solids include sludge and saltcake (see definitions below).			
Supernate (1)	May be either measured or estimated. Supernate is either the estimated or measured liquid floating on the surface of the waste or under a floating solids crust. In-tank photographs or videos are useful in estimating the liquid volumes; liquid floating on solids and core sample data are useful in estimating large liquid pools under a floating crust.			
Drainable Interstitial Liquid (DIL) (1)	This is initially calculated. Drainable interstitial liquid is calculated based on the saltcake and sludge volumes, using calculated porosity values from past pumping or actual data for each tank. Interstitial liquid is liquid that fills the interstitial spaces of the solids waste. The sum of the interstitial liquid contained in saltcake and sludge minus an adjustment for capillary height is the initial volume of drainable interstitial liquid.			

COLUMN HEADING	COLUMN VOLUME CALCULATIONS (Underlined)/DEFINITIONS
Pumped This Month	Net total gallons of liquid pumped from the tank during the month. If supernate is present, pump production is first subtracted from the supernatant volume. The remainder is then subtracted from the drainable interstitial liquid volume.
Total Pumped (1)	Cumulative net total gallons of liquid pumped from 1979 to date.
Drainable Liquid Remaining (DLR) (1)	Supernate plus Drainable Interstitial Liquid. The total Drainable Liquid Remaining is the sum of drainable interstitial liquid and supernate.
Pumpable Liquid Remaining (PLR) (1)	Drainable Liquid Remaining minus unpumpable volume. Not all drainable interstitial liquid is pumpable.
Sludge	Solids formed during sodium hydroxide additions to waste. Sludge usually was in the form of suspended solids when the waste was originally received in the tank from the waste generator. In-tank photographs or videos may be used to estimate the volume.
Saltcake	Results from crystallization and precipitation after concentration of liquid waste, usually in an evaporator. If saltcake is layered over sludge, it is only possible to measure total solids volume. In-tank photographs or videos may be used to estimate the saltcake volume.
Solids Volume Update	Indicates the latest update of any change in the solids volume.
Solids Update Source - See Footnote	Indicates the source or basis of the latest solids volume update.
Last In-tank Photo	Date of last in-tank photographs taken.
Last In-tank Video	Date of last in-tank video taken.
See Footnotes for These Changes	Indicates any change made the previous month. A footnote explanation for the change follows the Inventory and Status by Tank Appendix (Table E-6).

(1) As pumping continues, supernate, DIL, DLR, PLR, and total gallons pumped are adjusted accordingly based on actual pump volumes.

## APPENDIX I

# TANK FARM CONFIGURATION, STATUS AND FACILITIES CHARTS




Figure I-1. High-Level Waste Tank Configuration




Figure I-2. Double-Shell Tank Instrumentation Configuration




Figure I-3. Single-Shell Tank Instrumentation Configuration

THE TANK FARM FACILITIES CHARTS (colored foldouts)

ARE ONLY BEING INCLUDED IN THIS REPORT ON A QUARTERLY BASIS

(i.e., months ending March 31, June 30, September 30, and December 31)

NOTE: COPIES OF THE FACILITES CHARTS CAN BE OBTAINED FROM DENNIS BRUNSON, LMSI MULTI-MEDIA SERVICES 376-2345, G3-51

ALMOST ANY SIZE IS AVAILABLE, WHICH CAN BE LAMINATED

P-CARD IS REQUIRED

This page intentionally left blank

### **DISTRIBUTION**

#### Number of copies

#### OFFSITE - USA

2 Congress of the United States

U.S. Senate

717 Hart Senate Building Washington D.C. 20510

Senator Ron Wyden

U. S. House of Representatives 1323 Longworth House Office Building Washington D. C. 20515

Congressman Richard "Doc" Hastings, 4th District Atten: Jeff Markey

4 U. S. Department of Energy-Headquarters

1000 Independence Avenue, SW Washington, D. C. 20585

H. Calley

EM-38 Cloverleaf Bldg.

Willam M. Levitan

EM-1 FORS/5A-014

U. S. Department of Energy-Headquarters

19901 Germantown Rd Germantown, MD 20874

Kurt Juroff

EM-44

Ralph Lightener

EM-44

1 U. S. Nuclear Regulatory Commission

Division of Fuel Cycle, Safeguards & Security Mail Stop T8-A33

Washington, DC 20555

Robert Pierson, Chief FSPB/FCSS (ADDRESSEE ONLY)

2 Washington State Department of Ecology

Nuclear & Mixed Waste Management Program

P.O. Box 47600

Olympia, WA 98504-7600

Library

Washington State Department of Ecology

Nuclear Waste Program 300 Desmond Drive Lacey, WA 98504

R. Stanley

1 Washington State Department of Health Radiation Protection 7171 Cleanwater Lane P. O. Box 47827 Olympia, WA 98504-7827 Allen W. Conklin 1 Oregon State Department of Energy 625 Marion St. NE, Suite 1 Salem, OR 97301 Dirk Dunning Do not remove from distribution without permission from ODOE 1 Oak Ridge National Laboratory P. O. Box 2008 Oak Ridge, TN 37831-6180 C. Forsberg MS-6180 1 Donald T. Oakley 9612 Hall Road Potomac, MD 20854 1 Foster-Miller, Inc. Power Systems Technology Group 350 Second Avenue Waltham, MA 02451-1196 Maureen Williams 1 **MACTEC** 

8310 Centerbrook Place Alexandra, VA 22308

Stanley Blacker, Vice President

1 Framatome Advanced Nuclear Power

3315 Old Forrest Rd Lynchburg, VA 24506

Brian Butler

#### TRI-CITIES:

1 ARES Corporation 636 Jadwin Ave., Suite B Richland, WA 99352

1 Babad Technical Services

2540 Cordoba Court Richland, WA 99352

. 1	Wastren Inc. 1050 Gilmore Ave, Suite C Richland, WA 99352 Gary Dunford	
ONSITE		
1	<b>BAT</b> R. T. Winward	H6-60
1	MACTEC - ERS J. F. Bertsch	B1-42
1	General Accounting Office C. R. Abraham	A1-80
1	Washington State Department Library	of Ecology B5-18
1	U. S. Environmental Protection D. R. Sherwood	Agency B5-01
7	U.S. Department of Energy	
	D. C. Bryson Wen-Shou Liou J. Polehn M. J. Royack A. B. Sidpara D. J. Williams Reading Room	H6-60 H6-60 H6-60 H6-60 H6-60 H2-53
2	Pacific National Northwest Lal	poratories
	J. L. Huckaby B. E. Opitz	K7-15 K6-75
85	CH2M Hill (CHG), and Affilia	ted Companies
	D. I. Allen K. M. Bowen V. C. Boyles D. L. Cartile R. J. Cash C. Defigh-Price M. P. Delozier M. L. Dexter (12) R. A. Dodd A. F. Erhart S. D. Estey J. G. Field L. A. Fort K. D. Fowler	S5-07 R2-12 R2-11 T4-07 R1-44 T4-08 H6-08 R1-51 S5-07 R3-73 R2-11 R2-12 R2-12
	C. T. Frantau	T4 00

G. T. Frater

B. C. Gooding

J. R. Freeman-Pollard

T4-08

R1-57

T4-07

B. M. Hanlon (10)	R3-72
D.C. Hedengren	R2-11
C. C. Hendersen	B2-05
B. A. Higley	R3-73
S. W. Hildreth	T4-07
K. M. Hodgson	R2-14
T. M. Hohl	R3-73
B. A. Johnson	S7-02
G. D. Johnson	R1-44
T. E. Jones	HO-22
J. Kalia	R1-43
M. R. Kembel	S7-03
R. A. Kirkbride	R3-73
P. F. Kison	T4-07
N. W. Kirch	R2-11
J. S. Konyu	S7-64
G. M. Koreski	R2-11
J. G. Kristofzski	R2-50
J. A. Lechelt	R2-11
P. Ohl	H4-01
M. A. Payne	H6-63
R. E. Pohto	R2-84
R. E. Raymond (2)	T4-08
W. E. Ross	S7-83
N. J. Scott-Proctor	S5-00
P. P. Sederburg	R2-50
J. N. Strode	R2-11
D. D. Taylor	H6-64
R. R. Thompson	T4-08
R. R. Thompson D. T. Vladimiroff	S7-20
A. E. Young (10)	R1-10
Central Files	B1-07
200 West Shift Office	T4-00
200 East Shift Office	S5-04
Environmental	
Data Mgmt Center (2)	H6-08
Unified Dose Assessment	110 00
Center (UDAC)	A0-20
Document Processing Center	A3-94